



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>RUSH</u>

PROJECT INFORMATION

1. Client: <u>NYC-BOE</u>	2. Project Name: <u>H.S. FOR LEADERSHIP & PUBLIC SERVICE (M834)</u>	3. Project #: <u>14584-0864</u>	4. Project Monitor: _____	4c. Rotameter Number: <u>HP-53</u>
2a. Project Address: <u>90 TRINITY PLACE, NY NY 10006</u>		4a. Air Sampler: <u>ALEX KHOLODENKO</u>		
5. Date: <u>6/11/02</u>	6. Abatement Location: <u>AS PER PROTOCOL</u>	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>01205716</u>	
9. Type		a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other		

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
-01-02				Field Blank <u>open side/closed</u>									
-03				Field Blank <u>Sealed</u>									
-04				Outside of the school adj. to main entrance	07:46	11:35	229	8.0	8.0	8.0	1832		
-05				North/West Side of the vestibule - 1 st floor	07:48	11:36	228	8.0	8.0	8.0	1824		
-06				Outside of Roof adj. to HVAC intake	07:51	11:40	229	8.0	8.0	8.0	1832		
-07				1 st floor - cafeteria south side	07:56	11:43	227	8.0	8.0	8.0	1816		
-08				2 nd floor - auditorium - west	08:03	11:50	227	8.0	8.0	8.0	1816		
-09				Basement - at back West side of the gym	08:07	11:54	227	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date	21. Time
I. <u>[Signature]</u>	<u>[Signature]</u>	<u>6/11/02</u>	<u>12:00</u>
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>VEU</u>	23. Date	24. Time	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>[Signature]</u>	<u>6/12/02</u>	<u>1:00</u>	
b. QC By:			
c. Lab Batch #:			

26. ATC Project Manager: <u>MARK TERIESEN</u>	27. Results To: <u>YANNIS EFSTATHIOU EXT 211</u> Beeper/Phone #'s <u>646-772-1155</u>
--	--

28. Comments:

 Analysis Methodology
 PCM - NIOSH 7400A
TEM - AHERA



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

TURNAROUND TIME				
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard	
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>RUSH</u>	

PROJECT INFORMATION

8055

1. Client: <u>NYC-BOE</u>	2. Project Name: <u>H.S. FOR LEADERSHIP & PUBLIC SERVICE (21894)</u>	3. Project #: <u>14584-0864</u>	4. Project Monitor: _____	4c. Rotameter Number: <u>HP-53</u>
2a. Project Address: <u>90 TRINITY PLACE, NY NY 10006</u>		4a. Air Sampler: <u>ALEX KHOLODENKO</u>		
5. Date: <u>6/11/02</u>	6. Abatement Location: <u>AS PER PROTOCOL</u>	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>01205916</u>	9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
-10				Outside of the school adj. to main entrance	1135	15:21	226	8.0	8.0	8.0	1808		
-11				North/West side of the vestibule - 1 st floor	1136	15:23	227	8.0	8.0	8.0	1816		
-12				At Building Door, adj. to HVAC intake	1140	15:27	227	8.0	8.0	8.0	1816		
-13				13 th floor hallway & elevators	15:30	19:18	228	8.0	8.0	8.0	1824		
-14				10 th floor - Room # 1005 South	15:33	19:22	229	8.0	8.0	8.0	1832		
-15				9 th floor - hallway by elevators	1537	19:24	227	8.0	8.0	8.0	1816		

CHAIN OF CUSTODY

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

18. Relinquished By: <u>[Signature]</u>	19. Received By: <u>[Signature]</u>	20. Date: <u>6/11/02</u>	21. Time: <u>2:00</u>	22. Lab Name: <u>FECH</u>	23. Date: <u>6/12/02</u>	24. Time: <u>1:00</u>	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
III.				c. Lab Batch #:			
26. ATC Project Manager: <u>MARK TERIESEN</u>		27. Results To: <u>YANNIS EFSTATHIOU EXT# 211</u> Beeper/Phone #s: <u>646-772-1155</u>		28. Comments:		Analysis Methodology PCM - NIOSH 7400A <u>TEM - AHERA</u>	



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

 Page 3 of 3

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>RUSH</u>

PROJECT INFORMATION

8053

1. Client: <u>NYC-BOE</u>		2. Project Name: <u>H.S. FOR LEADERSHIP & PUBLIC SERVICE (M894)</u>		3. Project #: <u>14584-0864</u>		4. Project Monitor: _____		4c. Rotameter Number: <u>HP-53</u>	
		2a. Project Address: <u>90 TRINITY PLACE, NY NY 10006</u>				4a. Air Sampler: <u>ALEX KHOLODENKO</u>			
5. Date: <u>6/11/02</u>		6. Abatement Location: <u>AS PER PROTOCOL</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacturer _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacturer <u>MMI</u> Lot # <u>01205916</u>		9. Type a. ☐ Background f. ☐ Environmental b. ☐ Pre-Abate d. ☐ Post-Abate g. ☒ Ambient c. ☐ Abatement e. ☐ OSHA h. ☐ Other _____	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. FCC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
-16				8 th Floor - Room # 809 - South	15:41	19:28	227	8.0	8.0	8.0	1816		
-17				7 th Floor - hallway by elevators	15:44	19:32	228	8.0	8.0	8.0	1824		
-18				6 th floor - Room # 602	15:48	19:35	227	8.0	8.0	8.0	1816		
-19				5 th floor - hallway by stairs "A"	15:51	19:40	229	8.0	8.0	8.0	1832		
-20				4 th floor - Room # 403 - Center	15:56	19:43	227	8.0	8.0	8.0	1816		
-21				3 rd floor - hallway by elevators	16:00	19:48	228	8.0	8.0	8.0	1824		

CHAIN OF CUSTODY

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

18. Relinquished By: _____		19. Received By: <u>MI</u>		20. Date: <u>6/11/02</u>	21. Time: <u>20:10</u>	22. Lab Name: <u>TEC</u>		23. Date: _____	24. Time: _____	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079	
I. _____						a. Analyzed By: <u>[Signature]</u>					
II. _____						b. QC By: _____					
III. _____						c. Lab Batch #: _____				Analysis Methodology PCM - NIOSH 7400A <u>TEM-APEBA</u>	
26. ATC Project Manager: <u>MARK TERIESEN</u>		27. Results To: <u>YANNIS EFSTATHIOU EXT # 211</u> Beeper/Phone #'s: <u>646-772-1155</u>				28. Comments: _____					

CITY_21MC100_003094333