



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

PROJECT INFORMATION

1. Client: NYC-BOE

2. Project Name: H.S. FOR LEADERSHIP & PUBLIC SERVICE (H834)

3. Project #: 14584-0864

4. Project Monitor: ALEX KHOLODENKO

4c. Rotameter Number: HP-53

2a. Project Address: 90 TRINITY PLACE, NY NY 10006

5. Date: 6/14/02

6. Abatement Location: AS PER PROTOCOL

7. ☐ RCM (0.8 micron MCE)

8. ☒ TEM (0.45 micron MCE)

9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement

10. Environmental d. ☐ Post-Abate e. ☐ OSHA f. ☒ Ambient g. ☐ Other

Cassette/Filler Manufacturer: MMI

Lot #: 01205916

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. FCC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
-01/02				Field Blank									
-03				Field Blank									
-04				Outside of Hec School adj to main entrance	07:50	11:37	227	8.0	8.0	8.0	1816		
-05				North/West side of the vestibule - 1st Floor	07:51	11:39	228	8.0	8.0	8.0	1824		
-06				On the roof, adj to HVAC intake	07:56	11:43	227	8.0	8.0	8.0	1816		
-07				14th floor - students cafeteria - south	08:04	11:51	227	8.0	8.0	8.0	1816		
-08				2nd floor - west side of auditorium	08:10	11:59	229	8.0	8.0	8.0	1832		
-09				Basement - at south side of gym	08:14	12:01	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I. <u>[Signature]</u>	<u>H. G. [Signature]</u>	<u>6/14/02</u>	<u>21:00</u>
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>TEC</u>	23. Date: <u>6/15</u>	24. Time: <u>3:00</u>	25. Microscope Make/Serial #
a. Analyzed By: <u>[Signature]</u>			☐ Nikon Labophot 238913
b. QC By:			☐ Nikon Labophot 238917
c. Lab Batch #:			☐ Nikon Labophot 239079

26. ATC Project Manager:
MARY TENISSEN

27. Results To: YANNIS EPSTATHIOU EXT#211
Beeper/Phone #'s 646-772-1155

28. Comments:

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA



8/10

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3

TURNAROUND TIME				
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard	
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>RUSH</u>	

PROJECT INFORMATION

1. Client: NYC-BOE		2. Project Name: H.S. FOR LEADERSHIP & PUBLIC SERVICE (M834)		3. Project #: 14584-0864		4. Project Monitor: _____		4c. Rotameter Number: HP-53	
5. Date: 6/14/02		6. Abatement Location: AS PER PROTOCOL		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture MMI Lot # 01205716		9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
-10				Outside of the school adj. to main entrance	1137	15:25	228	8.0	8.0	8.0	1824		
-11				North/West side of vestibule - 1 st floor	1139	15:26	227	8.0	8.0	8.0	1816		
-12				On roof, adj. to HVAC intake	1143	15:30	227	8.0	8.0	8.0	1816		
-13				13 th floor - hallway, adj. to elevators	1532	19:20	228	8.0	8.0	8.0	1824		
-14				10 th floor - Room 606 East	15:36	19:24	228	8.0	8.0	8.0	1824		
-15				9 th floor - hallway adj. to stairs "B"	15:40	19:28	228	8.0	8.0	8.0	1824		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
I. <u>[Signature]</u>	<u>H. G. [Signature]</u>	<u>6/14/02</u>	<u>21:00</u>
II.			
III.			

LAB INFORMATION

(ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>TEC</u>	23. Date	24. Time	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>[Signature]</u>	<u>6/15</u>	<u>5:00</u>	
b. QC By:			
c. Lab Batch #:			

26. ATC Project Manager: MAUR TENISSEN	27. Results To: YANNIS EFSTATHIOU EXT# 211 Beeper/Phone #'s 646-772-1155
--	---

28. Comments:

 Analysis Methodology
 PCM - NIOSH 7400A
 TEM - AHERA

CITY_21MC100_003094389



8110

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☒ Other <u>RUSH</u>

PROJECT INFORMATION

1. Client: <u>NYC-BOE</u>	2. Project Name: <u>H.S. FOR LEADERSHIP & PUBLIC SERVICE (M894)</u>	3. Project #: <u>14584-0864</u>	4. Project Monitor: _____	4c. Rotameter Number: <u>HP-53</u>
5. Date: <u>6/14/02</u>	6. Abatement Location: <u>AS PER PROTOCOL</u>	7. ☐ PCM (0.8 micron MCE) Cassette/Filler Manufacture _____ Lot # _____	8. ☒ TEM (0.45 micron MCE) Cassette/Filler Manufacture <u>MMI</u> Lot # <u>0/205916</u>	9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other _____

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
-16				8 th floor - Room #809 Center	15:43	19:52	229	8.0	8.0	8.0	1832		
-17				7 th floor - hallway By water fountain	15:46	19:36	230	8.0	8.0	8.0	1840		
-18				6 th floor - Room 602 South	15:49	19:40	231	8.0	8.0	8.0	1848		
-19				5 th floor - hallway adj. to elevators	15:53	19:44	231	8.0	8.0	8.0	1848		
-20				4 th floor - Room 403 West	15:56	19:48	232	8.0	8.0	8.0	1856		
-21				3 rd floor - hallway adj. to stairs "A"	16:01	19:51	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By	20. Date	21. Time
<u>I. [Signature]</u>	<u>N. G. [Signature]</u>	<u>6/14/02</u>	<u>21:00</u>
II.			
III.			

LAB INFORMATION

(ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>TEC</u>	23. Date	24. Time	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>[Signature]</u>			
b. QC By:			
c. Lab Batch #:			

26. ATC Project Manager:
MARK TERIESEN

27. Results To: YANNIS EFSTATHIOU EXT#211
Beeper/Phone #'s: 646-772-1155

28. Comments:

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

CITY_21MC100_003094390