



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 4

PROJECT INFORMATION

1. Client: NYC - BOE		2. Project Name: New Stuyvesant HS (M477)		3. Project #: 87468-87491		4. Project Monitor: HERANT ANTONYAN		4c. Rotameter Number: HP-88	
5. Date: 4/30/02		6. Abatement Location: Exterior, Interior of the bldg. & the Ref		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture Metty Metric Lot # 01205916		9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other **Rush**

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
22				<u>Field Blank</u>									
23				<u>Field Blank</u>									
1				<u>5th floor Cafeteria</u>	<u>7:00</u>	<u>11:00</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		
2				<u>3rd floor Aux Gym</u>	<u>7:03</u>	<u>11:03</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		
3				<u>Inside the Pool area</u>	<u>7:06</u>	<u>11:06</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		
4				<u>Inside the Auditorium</u>	<u>7:09</u>	<u>11:09</u>	<u>240</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1920</u>		
5				<u>Outside of the building</u> <u>North side</u>	<u>7:12</u>	<u>11:13</u>	<u>241</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1928</u>		
6				<u>Outside the building</u> <u>East side</u>	<u>7:15</u>	<u>11:16</u>	<u>241</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1928</u>		

CHAIN OF CUSTODY

18. Relinquished By: I. H. [Signature]	19. Received By: [Signature]	20. Date: 4/30/02	21. Time: 8
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC ELAP	23. Date: 4/30/02	24. Time: 23:15	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: [Signature]			
b. QC By:			
c. Lab Batch #:			Analysis Methodology PCM - NIOSH 7400A TEM - AIEFA
26. ATC Project Manager: Yiannis Efsthathiou			
27. Results To: Yiannis Efsthathiou Beeper/Phone #'s (646) 772-1155			28. Comments:

CITY_21MC100_003095882



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 4

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Name: New Stuyvesant HS (M477)	3. Project #: 19125-0246	4. Project Monitor: HERANT ANTONYAN	4c. Rotameter Number: HP-88
5. Date: 4/30/02	6. Abatement Location: Exterior, Interior of the bldg. & the Roof	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot #	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture Lot #	9. Type a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location	13. Time (24 hrs clock)	14. Flow Rate (L/min.)	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA 12b. OWA 12c. Sample Coordinates	13a. Start 13b. End 13c. Total	14a. Start 14b. End 14c. Avg			
24		Field Blank <i>Sealed blank</i>					
		Field Blank					
7		<i>Outside the building South side</i>	7:18 11:19 241	8 8 8	1928		
8		<i>1st floor lobby area</i>	7:21 11:23 242	8 8 8	1936		
9		<i>2nd floor lobby area</i>	7:22 11:24 242	8 8 8	1936		
10		<i>Outside the building 11th floor Roof.</i>	7:29 11:33 244	8 8 8	1952		
11		<i>Outside the building North side</i>	11:13 15:14 244	8 8 8	1928		
12		<i>Outside the building East side</i>	11:16 15:17 241	8 8 8	1928		

CHAIN OF CUSTODY

18. Relinquished By: I. <i>H. [Signature]</i> II. III.	19. Received By: <i>[Signature]</i>	20. Date: 4/30/02	21. Time
---	--	-----------------------------	----------

LAB INFORMATION

(ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC DECA	23. Date: 4/30/02	24. Time: 15:15	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <i>[Signature]</i>	b. QC By:	c. Lab Batch #:	

26. ATC Project Manager: Yiannis Efsthathiou	27. Results To: Yiannis Efsthathiou Beeper/Phone #'s: (646) 772-1155
--	---

28. Comments:	Analysis Methodology PCM - NIOSH 7400A REM - AHERA
---------------	---

CITY_21MC100_003095883



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name: <u>New Stuyvesant HS (M477)</u>		3. Project #: <u>19125-0246</u>		4. Project Monitor: <u>HERANT ANTONYAN</u>		4c. Rotameter Number: <u>HP-88</u>	
5. Date: <u>4/30/02</u>		6. Abatement Location: <u>Exterior, Interior of the bldg. & the Roof</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type a. ☐ Background f. ☐ Environmental b. ☐ Pre-Abate d. ☐ Post-Abate g. ☒ Ambient c. ☐ Abatement e. ☐ OSHA h. ☐ Other _____	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
13				<u>Outside the building South side</u>	11:19	15:20	241	8	8	8	1928		
14				<u>1st floor lobby area</u>	11:23	15:23	240	8	8	8	1920		
15				<u>2nd floor lobby area</u>	11:24	15:24	240	8	8	8	1920		
16				<u>Outside the building 11th floor Roof</u>	11:33	15:35	242	8	8	8	1936		
17				<u>7th floor, Rm. 701 E</u>	14:51	18:52	241	8	8	8	1928		
18				<u>8th floor, Rm. 839 S.</u>	14:45	18:47	242	8	8	8	1936		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I. <u>H. Anthony</u>	<u>ATC</u>	<u>4/30/02</u>	<u>8</u>
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC PCM</u>	23. Date:	24. Time:	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>ATC</u>	<u>4/30/02</u>	<u>15:00</u>	
b. QC By:			
c. Lab Batch #:			Analysis Methodology PCM - NIOSH 7400A <u>TEM - ATC</u>
28. Comments:			

26. ATC Project Manager: <u>Yiannis Efsthion</u>	27. Results To: <u>Yiannis Efsthion</u> Beeper/Phone #'s <u>(646) 772-1155</u>
---	---

CITY_21MC100_003095884



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 4 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name: <u>New Stuyvesant HS (M477)</u>		3. Project #: <u>19125-0246</u>		4. Project Monitor: <u>HERANT ANTONYAN</u>		4c. Rotameter Number: <u>HP-88</u>	
		2a. Project Address:				4a. Air Sampler:			
5. Date: <u>4/30/02</u>		6. Abatement Location: <u>Exterior, Interior of the Bldg. & the Roof</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type a. ☐ Background ☐ Environmental b. ☐ Pre-Abate d. ☐ Post-Abate g. ☒ Ambient c. ☐ Abatement e. ☐ OSHA h. ☐ Other _____	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc F/CC
		12a IWA	12b OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
19				<u>9th floor, Rm. 938 N.</u>	<u>14:42</u>	<u>18:44</u>	<u>242</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1936</u>		
20				<u>9th floor, Hallway</u>	<u>14:40</u>	<u>18:41</u>	<u>241</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1928</u>		
21				<u>8th floor Hallway</u>	<u>14:37</u>	<u>18:38</u>	<u>241</u>	<u>8</u>	<u>8</u>	<u>8</u>	<u>1928</u>		

CHAIN OF CUSTODY

18. Relinquished By: <u>I. H. [Signature]</u>	19. Received By: <u>[Signature]</u>	20. Date: <u>4/30/02</u>	21. Time:
II.			
III.			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC [Signature]</u>	23. Date: <u>4/30/02</u>	24. Time: <u>15:00</u>	25. Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>[Signature]</u>			
b. QC By:			
c. Lab Batch #:			

26. ATC Project Manager: <u>Yiannis Efsthathiou</u>	27. Results To: <u>Yiannis Efsthathiou</u> Beeper/Phone #'s <u>(646) 772-1155</u>
--	--

28. Comments:	Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
---------------	--

CITY_21MC100_003095885