

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

Attn: U.S. EPA - Residential
HQ Financial Services Division
1200 Pennsylvania Ave. NW Maildrop 2734R
Washington, DC 20480

Customer ID: USEPA44
Customer PO: 2W-1103-NNLX
Received: 12/13/01 2:05 PM

Fax: Phone:
Project: USPHS Mission #12 Residential Sampling New York
City Bldg 6,7,12-23,26,29,31-34

EMSL Order: 030109702
EMSL Project ID:
Analysis Date 12/14/01

55 Liberty St

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	MATRIX MATERIAL	NON-ASBESTOS FIBERS	ASBESTOS TYPES	TOTAL ASBESTOS
(R)VA-R1-7 030109702-0001	RESIDENCE 1		100.0	None	No Asbestos Detected	
(R)VA-R2-7 030109702-0002 <i>Sur Home</i>	RESIDENCE 2		100.0	None	No Asbestos Detected	
(R)SA-07 030109702-0003	OUTDOORS <i>Outside Front Entrance</i>		98.3	None	1.7 Chrysotile	1.7
(R)VA-C-7 030109702-0004	COMMON AREA		100.0	None	No Asbestos Detected	
(R)VA-C-12 030109702-0005	COMMON AREA		100.0	None	No Asbestos Detected	
(R)VA-R1-12 030109702-0006	RESIDENCE 1		100.0	None	No Asbestos Detected	
(R)VA-P2-12 030109702-0007	RESIDENCE 2		100.0	None	No Asbestos Detected	
(R)VA-C-13 030109702-0008	COMMON AREA		100.0	None	No Asbestos Detected	
(R)VA-R1-13 030109702-0009	RESIDENCE 1		100.0	None	No Asbestos Detected	
(R)VA-R2-13 030109702-0010	RESIDENCE 2		100.0	None	No Asbestos Detected	
(R)VA-C-14 030109702-0011	COMMON AREA		100.0	None	No Asbestos Detected	

Analyst

Eric B. B.
Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc.
ACCREDITATIONS: NALAP #01043-0 and NY STATE ELAP #11505

NY DOB-

1

TOTAL P.03

CITY_21MC100_011118056