



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

REPORT OF AIR MONITORING

(PHASE CONTRAST MICROSCOPY ANALYSIS OF AIR FILTERS)

CLIENT: GPS Environmental Consultants, Inc.

DATE: 05/19/02

PROJECT: MERRILL LYNCH

ADDRESS: 222 Broadway, New York, NY

16th Floor - Roof D Setback Clean Up

[illegible]

TYPE OF RESPIRATORS:

TYPE OF WORK:

1 = HALF FACE, 2 = PAPR, 3 = TYPE C, 4 = OTHER (SPECIFY):

1= BLDG DECON, 2= PLASTICIZING, 3= GROSS REMOVAL, 4= GLOVEBAG, 5= CLEANING,
6= ENCAPSULATION, 7= BAGOUT, 8= OTHER (SPECIFY):

SAMPLING TECHNICIAN: Darryl L. (Client)

ROTAMETER:

DATE RECEIVED: 05/20/02

DATE OF ANALYSIS: 05/20/02

DATE OF REPORT: 05/21/02

Analyst:

Gopichand Yallabandi

Lab Manager:

David Chen

The samples listed above are analyzed by Phase Contrast Microscopy (PCM) as per NIOSH 7400 Method -Issue 3. The detection limit of this method is 7 fibers per square mm per filter area. KAM CONSULTANTS shall not be liable for information arising from samples that are not in its QA and QC program.

The results relate only to the items calibrated or tested. The certificate of report shall not be reproduced without approval of the laboratory

The report must not be used by the client to claim endorsement by NVLAP or any agency of the U.S. Government.

NYS-DOH ELAP # 11273

AIHA # 100269