

H.A. Bader Consultants, Inc.
88 Bleecker Street, Suite 4E
New York, New York 10012
(212) 475 - 4122

PROJECT NAME: DC 37
PROJECT ADDRESS: 115 Chambers Street, NY, NY
TAKEN BY: Rm + HB

ASBESTOS AIR SAMPLING

DATE 2001	SAMPLE LOCATION	PUMP NUMBER	SAMPLE NUMBER	FLOW RATE (L/MIN)	START TIME	STOP TIME	TOTAL TIME	TOTAL VOLUME	A	M	I	O	P	B	S	R	C	F	E
10/19	Basement Lounge	33	D1	10	1332	1542	135	1350	X					X					X
10/19	Basement Office	28	D2	10	1333	1548	135	1350	X					X					X
10/19	1st Floor	62	D3	10	1307	1542	155	1550	X					X					X
10/19	2nd Floor	13	D4	10	1312	1543	151	1510	X					X					X
10/19	3rd Floor	2	D5	10	1318	1544	146	1460	X					X					X
10/19	4th Floor	30	D6	10	1325	1549	140	1400	X					X					X
10/19	Field Blank	—	D7	—	—	—	—	—											

A = Air Sampling
M = Micro-Vacuum Sampling
I = Inside Work Area

O = Outside Work Area
P = Pre Air Sampling
B = Baseline/Ambient

S = Preparation
R = During Removal
C = Cleanup

F = Final Air Test
E = Pumps Calibrated at Start/Finish

Page 01 of 01