

CENTRAL ARTERY (I-93),
ENVIRONMENTAL OPERATIONS
AIR QUALITY INSPECTION SHEET

P. 1 of 1Inspection Date: 06/24/02Inspector: JF DOLANWeather: CLEAR SKY
75-80F APPROX.

Time of Inspection	Contract Number	Work Area Inspected	Dirt/Mud tracked onto Public Roadways	Windblown Dust/Dirt from the Work Area	Diesel Emissions from the Work Area	Observations/Recommendations
1130H	C17A3 C17A9	ATLANTIC AND NORTHERN	N	N	N	NO DIRT TRACKING; NO ON-SITE AIRBORNE DUST; OR NO DIESEL EMISSIONS OBSERVED
1155H	C08A1	BREMEN AND MARION	N	N	N	WATER TRUCK OBSERVED IN USE IN CONTRACTOR'S LAYDOWN AREA ADJACENT TO BREMEN ST.
1310H	C29D1 C19B1	NASHUA AND MINOT	N	N	N	WATER TRUCK OBSERVED IN USE IN C29D1 WORK AREA.
1330H	C15A2	N. WASHINGTON AND MEDFORD	N	Y	N	AIRBORNE DUST OBSERVED IN CONTRACTOR'S WORK AREA AT RIP VALENTI AND N. WASHINGTON
1400H	C09C4 C09A4	ALBANY AND E. BERKELEY	N	N	N	NO DIRT TRACKING; NO ON-SITE AIRBORNE DUST; OR NO DIESEL EMISSIONS OBSERVED
1420H	C01A6	A STREET AREA	N	N	N	WATER TRUCK OBSERVED IN USE ON NECCO AND A STREET, AND GARAGE ACCESS ROAD.
1430	C21S2	TIDE AND F. KENNEDY	N	N	N	WATER TRUCK OBSERVED IN USE ON TIDE STREET AND FID KENNEDY AVENUE.