

RJ LeeGroup, Inc.350 Hochberg Road, Monroeville, PA 15146
Phone: (724) 325-1776 Fax: (724) 733-1799**Final Laboratory Report**
TEM Air AnalysisRJ Lee Group, Inc.
350 Hochberg Road
Monroeville, PA 15146
USAReport Date: 7/8/2004
Sample Receipt Date: 7/7/2004
RJ Lee Group Job No.: ATH306366-851
Samples Received: 19
Building: 130 Liberty

Method: Federal Register, 40 CFR, Part 763, October 30, 1987

RJLG Sample Number	Sample Type	Date Collected Start/Stop	Floor	Grid	Sub Location	Filter Area (mm ²)	Volume (liter)	Area Analyzed (mm ²)	Asbestos Structures Chry Amph	Concentration	
										Analytical Sensitivity (S/mm ²)	Analytical Sensitivity (S/cc)
5222708.HT	Area	7/4/2004 7/5/2004	0	Z	(South) - Decon Exit	385	2040.00	0.04365	0 0	< 22.9 22.9	< 0.004 0.004
5222709.HT	Area	7/4/2004 7/5/2004	0	FF	(South) - Shanty Area	385	1916.25	0.04365	0 0	< 22.9 22.9	< 0.005 0.005
5222710.HT	Area	7/4/2004 7/5/2004	0	Y	(South) - Decon Entrance	385	2044.00	0.04365	0 0	< 22.9 22.9	< 0.004 0.004
5222711.HT	Area	7/4/2004 7/5/2004	0	X	(South) - Ramp	385	2044.00	0.04365	0 0	< 22.9 22.9	< 0.004 0.004
5222712.HT	Field Blank	7/4/2004 7/4/2004	0	X	(South) - Ramp	385	0.000	0.08730	0 0	< 11.5 11.5	N/A N/A
5223611.HT	Area	7/4/2004 7/4/2004	0	FF	(South) - Shanty Area	385	1988.00	0.04365	0 0	< 22.9 22.9	< 0.004 0.004
5222718.HT	Area	7/4/2004 7/5/2004	1	K	(NorthWest) - Cedar Decon	385	2044.00	0.04365	1 0	22.9 22.9	0.004 0.004
5223610.HT	Area	7/4/2004 7/4/2004	0	Z	(South) - Decon Exit	385	1984.00	0.04365	0 0	< 22.9 22.9	< 0.004 0.004
5223612.HT	Area	7/4/2004 7/4/2004	0	Y	(South) - Decon Entrance	385	1984.00	0.04365	0 0	< 22.9 22.9	< 0.004 0.004
5223613.HT	Area	7/4/2004 7/4/2004	0	X	(South) - Ramp	385	1984.00	0.04365	0 0	< 22.9 22.9	< 0.004 0.004

Notes

1. Volumes provided by Ambient were used to calculate analytical results and sensitivities.
2. "<" indicates results less than analytical sensitivity. "-" indicates that sample was not analyzed.
3. Sample(s) for this project were analyzed at our Monroeville, PA (NYLAP #101268-0, NY ELAP #10844) facility.
4. If RJ Lee Group, Inc. did not collect the samples analyzed, the verifiability of the laboratory's results are limited to the reported values.
5. Abbreviations: N/A-Not Applicable, Chry-Chrysotile Asbestos, Amph-Amphibole Asbestos, S-Structures.
6. Samples will be held for 90 days and then disposed of per Federal regulations.
7. These results are submitted pursuant to RJ Lee Group's current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. No responsibility or liability is assumed for the manner in which these results are used or interpreted.

See Appendix A for fiber data.

Page 2 of 4


Jul 09 04 08:37a IBM USER
From: RJ Lee Group, Inc. To: Mr. Noel Drago732 6018
Date: 7/8/2004 Time: 8:48:16 AM

Page 3 of 4 p. 29

RJ Lee Group, Inc.**Laboratory Report (cont.)**RJ Lee Group Job No. ATH306366-851
Building: 130 LibertyRJ Lee Group, Inc.
Report Date: 7/8/2004

RJLG Sample Number	Sample Type	Date Collected Start Stop	Floor	Grid	Sub Location	Filter Area (mm ²)	Volume (liter)	Area Analyzed (mm ²)	Asbestos Structures Chry Amph	Concentration Analytical Sensitivity (S/m ²) (S/cc)
5223614.HT	Field Blank	7/4/2004 7/4/2004	0	X	(South) - Ramp	385	0.000	0.08730	0 0	< 11.5 11.5 N/A N/A
5223622.HT	Area	7/4/2004 7/4/2004	0	FF	(South) - Shanty Area	385	1852.00	0.04365	0 0	< 22.9 22.9 < 0.005 0.005
5223620.HT	Area	7/4/2004 7/4/2004	1	K	(NorthWest) - Cedar Decon	385	2136.00	0.04365	0 0	< 22.9 22.9 < 0.004 0.004
5223621.HT	Area	7/4/2004 7/4/2004	0	Z	(South) - Decon Exit	385	1856.00	0.04365	0 0	< 22.9 22.9 < 0.005 0.005
5223625.HT	Field Blank	7/4/2004 7/4/2004	0	X	(South) - Ramp	385	0.000	0.08730	0 0	< 11.5 11.5 N/A N/A
5223623.HT	Area	7/4/2004 7/4/2004	0	Y	(South) - Decon Entrance	385	1740.00	0.05238	0 0	< 19.1 19.1 < 0.004 0.004
5223624.HT	Area	7/4/2004 7/4/2004	0	X	(South) - Ramp	385	1860.00	0.04365	0 0	< 22.9 22.9 < 0.005 0.005
5223626.HT	Field Blank	7/4/2004 7/4/2004	99	Not Acquired	(NorthWest) - Washington and Cedar	385	0.000	0.08730	0 0	< 11.5 11.5 N/A N/A
5223631.HT	Area	7/4/2004 7/4/2004	1	K	(NorthWest) - Cedar Decon	385	1708.00	0.05238	0 0	< 19.1 19.1 < 0.004 0.004

Authorized Signature:


 /s/b
 Kimberly A. Allison, Manager - TEM Analysis
Notes:

1. Volumes provided by Ambient were used to calculate analytical results and sensitivities.
2. "<" indicates results less than analytical sensitivity. "..." indicates that sample was not analyzed.
3. Sample(s) for this project were analyzed at our: Monroeville, PA (NVLAP #101208-0, NY ELAP #10844) facility.
4. If RJ Lee Group, Inc. did not collect the samples analyzed, the verifiability of the laboratory's results are limited to the reported values.
5. Abbreviations: N/A-Not Applicable, Chry-Chrysotile Asbestos, Amph-Amphibole Asbestos, S-Structures.
6. Samples will be held for 90 days and then disposed of per Federal regulations.
7. These results are submitted pursuant to RJ Lee Group's current terms and conditions of sale, including the company's standard warranty and limitation of liability provisions. No responsibility or liability is assumed for the manner in which these results are used or interpreted.

See Appendix A for fiber data.

Page 3 of 4