



AIR MONITORING DATA AND

CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client <u>NYC-BOE</u>	2. Project Name <u>PS 1M</u>	3. Project # <u>14584-0869</u>	4. Project Monitor <u>A. Antonyan</u>	4c. Rotameter Number <u>HP-128</u>
5. Date <u>8/24/02</u>	6. Abatement Location <u>Throughout the bldg, & Roof</u>	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>	9. Type a. ☐ Background d. ☐ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA
f. ☐ Environmental g. ☒ Ambient h. ☐ Other				

DAILY AIR SAMPLE RECORD

10 Sample I.D. Number	11 Pump Number	12 Sample Location		13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c. Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14c Avg		
19				Field Blank								
20				Field Blank								
01				Outside by Main entrance	07:00	11:00	240	8.0	8.0	8.0	1920	
02				First floor lobby area	07:03	11:04	241	8.0	8.0	8.0	1928	
03				Cafeteria	07:06	11:06	240	8.0	8.0	8.0	1920	
04				Play area	07:10	11:10	240	8.0	8.0	8.0	1920	
05				Auditorium	07:13	11:14	241	8.0	8.0	8.0	1928	
06				2nd floor Hallway	07:17	11:17	240	8.0	8.0	8.0	1920	

CHAIN OF CUSTODY

18 Relinquished By <u>I H Today</u>	19 Received By <u>RRly</u>	20 Date <u>8/24/02</u>	21 Time <u>22:00</u>
27. Result To _____ Beeper/Phone #'s _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC TEM</u>	23 Date <u>8/25/02</u>	24 Time <u>14:00</u>	25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a Analyzed By <u>RRly</u>			
b QC By			
c Lab Batch #			
28. Comments.			
Analysis Methodology PCM - NIOSH 7400A TEM - AHERA			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003042250



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client <u>NYC-BOE</u>		2 Project Name <u>PS 1 M</u>		3 Project # <u>14584-0869</u>		4 Project Monitor <u>H. Antonyan</u>		4c Rotameter Number <u>HP-128</u>	
		2a Project Address <u>8 Henry Street NYM</u>		3a Task #					
5 Date <u>8/24/02</u>		6 Abatement Location <u>Throughout the bldg and roof</u>		7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>		9 Type a ☐ Background d ☐ Post-Abate b ☐ Pre-Abate e ☐ OSHA	
								f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location			13 Time (24 hrs clock)			14. Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c. Total	14a Start	14b End	14b Avg			
<u>21</u>				Field Blank <u>Sealed Blank</u>									
				Field Blank									
<u>07</u>	<u>1</u>			<u>Rm. 213</u>	<u>07:20</u>	<u>11:20</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		
<u>08</u>	<u>1</u>			<u>Rm. 202</u>	<u>07:24</u>	<u>11:24</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		
<u>09</u>	<u>1</u>			<u>3rd floor Hallway</u>	<u>07:28</u>	<u>11:29</u>	<u>241</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1928</u>		
<u>10</u>	<u>1</u>			<u>Rm. 313</u>	<u>07:31</u>	<u>11:33</u>	<u>242</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1936</u>		
<u>11</u>	<u>1</u>			<u>Rm. 301</u>	<u>11:32</u>	<u>15:32</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		
<u>12</u>	<u>1</u>			<u>4th floor Hallway</u>	<u>11:35</u>	<u>15:35</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		

CHAIN OF CUSTODY

18 Relinquished By		19 Received By		20. Date	21 Time
<u>I H. Antonyan</u>		<u>RRJ</u>		<u>8/24/02</u>	<u>22:00</u>
<u>II</u>					
<u>III</u>					

26 Project Manager	27 Result To _____ Beep/Phone #'s _____
--------------------	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC-TEM</u>		23 Date	24 Time	25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a Analyzed By <u>RRJ</u>		<u>8/24/02</u>	<u>14:20</u>	
b QC By				
c Lab Batch #				Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28 Comments				

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003042251



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client <u>NYC - BOE</u>		2 Project Name <u>PS 1 M</u>		3 Project # <u>14584-0869</u>		4 Project Monitor		4c Rotameter Number	
		2a Project Address <u>8 Henry Street, NY</u>		3a Task #		4a Air Sampler <u>H. Antonyan</u>		<u>HP-128</u>	
5 Date <u>8/24/02</u>		6 Abatement Location		7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>		9 Type	
								c ☐ Abatement d ☐ Post-Abate e ☐ OSHA f ☐ Environmental g ☒ Ambient h ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location			13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
				Field Blank									
				Field Blank									
13		1		Rm 413	11:40	15:40	240	8.0	8.0	8.0	1920		
14		1		Rm. 402	11:43	15:43	240	8.0	8.0	8.0	1920		
15		1		5th floor Hallway	11:50	15:50	240	8.0	8.0	8.0	1920		
16		1		Rm. 503	11:53	15:53	240	8.0	8.0	8.0	1920		
17		1		Rm. 501	11:56	15:56	240	8.0	8.0	8.0	1920		
18		1		Roof	12:02	15:59	237	8.0	8.0	8.0	1896		

CHAIN OF CUSTODY

18 Relinquished By		19 Received By		20 Date	21 Time
I <u>H. Antonyan</u>		<u>RRJ</u>		<u>8/24/02</u>	
II					
III					
26 ATC Project Manager				27. Result To _____ Beeper/Phone #'s _____	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC TEM</u>		23 Date	24 Time	25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a Analyzed By <u>RRJ</u>		<u>8/25/02</u>	<u>14:20</u>	
b QC By				
c Lab Batch #				28 Comments.
Analysis Methodology PCM - NIOSH 7400A TEM - AHERA				

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003042252