



AIR MONITORING DATA AND

CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1 Client <u>NYC-BOE</u>	2 Project Name <u>PS 1M</u>	3 Project # <u>14584-0869</u>	4 Project Monitor <u>H. Antonyan</u>	4c. Rotameter Number <u>HP-128</u>	
2a Project Address <u>8 Henry Street, NY, NY</u>		3a Task #			
5 Date <u>8/24/02</u>	6 Abatement Location <u>Throughout the bldg, 2 Roof</u>	7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____	8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>	9 Type a ☐ Background b ☐ Pre-Abate c ☐ Abatement d ☐ Post-Abate e ☐ OSHA	f ☐ Environmental g ☒ Ambient h ☐ Other

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location	13 Time (24 hrs clock)	14 Flow Rate (L/min)	15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA 12b OWA 12c Sample Coordinates	13a Start 13b End 13c Total	14a Start 14b End 14c Avg			
19		Field Blank					
20		Field Blank					
01		Outside by Main entrance	07:00 11:00 240	8.0 8.0 8.0	1920		
02		First floor lobby area	07:03 11:04 241	8.0 8.0 8.0	1928		
03		Cafeteria	07:06 11:06 240	8.0 8.0 8.0	1920		
04		Play area	07:10 11:10 240	8.0 8.0 8.0	1920		
05		Auditorium	07:13 11:14 241	8.0 8.0 8.0	1928		
06		2nd floor Hallway	07:17 11:17 240	8.0 8.0 8.0	1920		

CHAIN OF CUSTODY

18 Relinquished By <u>H. Antonyan</u>	19 Received By <u>RRKly</u>	20 Date <u>8/24/02</u>	21 Time <u>22:00</u>
27 Result To _____ Beeper/Phone #'s _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC TEM</u>	23 Date <u>8/25/02</u>	24 Time <u>14:00</u>
a Analyzed By <u>RRKly</u>		
b QC By		
c Lab Batch #		
28 Comments		
25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079		
Analysis Methodology PCM - NIOSH 7400A TEM - AHERA		

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003042275



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client NYC-BOE		2. Project Name PS1 M		3. Project # 14584-0869		4. Project Monitor H. Anjonyan		4c. Rotameter Number HP-128	
		2a. Project Address 8 Henry Street NY		3a. Task #		4a. Air Sampler H. Anjonyan			
5. Date 8/24/02		6. Abatement Location Throughout the bldg and Roof		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture MMI Lot # 02106916		9. Type a. ☐ Background c. ☒ Abatement b. ☐ Pre-Abate d. ☐ Post-Abate e. ☐ OSHA	
								f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample ID Number	11 Pump Number	12 Sample Location		12c. Sample Coordinates	13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA		13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
21				Field Blank Sealed Blank									
				Field Blank									
07		1		Rm. 213	07:20	11:20	240	8.0	8.0	8.0	1920		
08		1		Rm. 202	07:24	11:24	240	8.0	8.0	8.0	1920		
09		1		3rd floor Hallway	07:28	11:29	241	8.0	8.0	8.0	1928		
10		1		Rm. 313	07:31	11:33	242	8.0	8.0	8.0	1936		
11		1		Rm. 301	11:32	15:32	240	8.0	8.0	8.0	1920		
12		1		4th floor Hallway	11:35	15:35	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

18 Relinquished By I H. Anjonyan	19 Received By RRKly	20 Date 8/24/02	21 Time 22:00
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name ATC-ZEN	23 Date 8/24/02	24 Time 14:20	25 Microscope Make/Serial # ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By RRKly			
b. QC By			
c. Lab Batch #			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
28 Comments			

26 Project Manager	27 Result To _____ Beeper/Phone #'s _____
--------------------	--

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003042276



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client. <u>NYC - BOE</u>		2 Project Name <u>PS 1 M</u>		3 Project # <u>14584-0869</u>		4 Project Monitor		4c Rotameter Number	
		2a Project Address <u>8 Henry Street, NY</u>		3a Task #		4a Air Sampler <u>H. Antonyan</u>		<u>HP-128</u>	
5 Date <u>8/24/02</u>		6 Abatement Location		7 ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8 ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>		9 Type	
						c ☐ Abatement		f ☐ Environmental	
						a ☐ Background		d ☐ Post-Abate	
						b ☐ Pre-Abate		e ☐ OSHA	
								g ☒ Ambient	
								h ☐ Other	

DAILY AIR SAMPLE RECORD

10 Sample I.D. Number	11 Pump Number	12 Sample Location			13 Time (24 hrs clock)			14 Flow Rate (L/min)			15 Total Air Vol (liters)	16 # Fibers/Fields Minus Blank	17 Fiber Conc F/CC
		12a IWA	12b OWA	12c Sample Coordinates	13a Start	13b End	13c Total	14a Start	14b End	14b Avg			
				Field Blank									
				Field Blank									
13	1			Rm. 413	11:40	15:40	240	8.0	8.0	8.0	1920		
14	1			Rm. 402	11:43	15:43	240	8.0	8.0	8.0	1920		
15	1			5th floor Hallway	11:50	15:50	240	8.0	8.0	8.0	1920		
16	1			Rm. 503	11:53	15:53	240	8.0	8.0	8.0	1920		
17	1			Rm. 501	11:56	15:56	240	8.0	8.0	8.0	1920		
18	1			Roof	12:02	15:59	237	8.0	8.0	8.0	1896		

CHAIN OF CUSTODY

18 Relinquished By		19 Received By		20 Date	21 Time
I <u>H. Antonyan</u>		<u>RRJ</u>		<u>8/24/02</u>	
II					
III					
26. ATC Project Manager.					
27 Result To _____				Beeper/Phone #'s _____	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22 Lab Name <u>ATC TEM</u>		23 Date	24 Time	25 Microscope Make/Serial #	
a Analyzed By <u>RRJ</u>		<u>8/25/02</u>	<u>14:20</u>	☐ Nikon Labophot 238913	
b QC By				☐ Nikon Labophot 238917	
c Lab Batch #				☐ Nikon Labophot 239079	
28 Comments					
Analysis Methodology					
PCM - NIOSH 7400A					
TEM - AHERA					

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003042277