



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 148 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: NYC-BOE
 2. Project Name: H.S. of Economics and Finance (MCE)
 2a. Project Address: 100 Trinity Pl. NY, NY
 3. Project #: 14584-265
 3a. Task #: 01
 4. Project Monitor: M. BALOTA
 4a. Air Sampler: HP-128
 5. Date: 03.03.02
 6. Abatement Location: ENTIRE
 7. ☐ PCM (0.8 micron MCE)
 Cassette/Filter Manufacture: Nuclepore
 Lot #: 28.116.612
 8. ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture: Nuclepore
 Lot #: 28.116.612
 9. Type: ☐ Abatement ☐ Environmental
☐ Background ☐ Post-Abate ☒ Ambient
☐ Pre-Abate ☐ OSHA ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Filters Minus Blank	17. Fiber Conc. F/Vol
		12a. IWA	12b. OWA	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
01				Field Blank								
02				Field Blank								
03			✓	Outside the building - Roof South east corner	07.30	11.18	228	8.0	8.0	8.0	1824	
04		✓		8th floor - Cafeteria North west corner	07.32	11.20	228	8.0	8.0	8.0	1824	
05			✓	Staircase B (open staircase) At 7th floor landing	07.34	11.21	227	8.0	8.0	8.0	1816	
06		✓		1st floor - Auditorium Left side of the entrance	07.37	11.23	226	8.0	8.0	8.0	1808	
07		✓		1st floor - Lobby Next to Room # 102A	07.38	11.24	226	8.0	8.0	8.0	1808	
08			✓	Outside the building Adj. to Main Entrance	07.39	11.25	226	8.0	8.0	8.0	1808	

CHAIN OF CUSTODY

18. Relinquished By: M. Balota
 19. Received By: Fabrice
 20. Date: 03-03-02
 21. Time: 9:05
 26. ATC Project Manager: MARK TERJESEN
 27. Result To: Mark Terjesen
 Beeper/Phone #'s: ATC ext 266

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: TEM
 a. Analyzed By: CPH
 b. QC By: 3/6 11:30
 c. Lab Batch #:
 23. Date: 3/6
 24. Time: 11:30
 25. Microscope Make/Model #: Hikon Laboprobe 230015
 Analysis Methodology: PCM - NIOSH 7400A
TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Push

PROJECT INFORMATION

1. Client: <u>NYC - BOC</u>		2. Project Name: <u>H.S. of Economics and Finance (NIBSS)</u>		3. Project #: <u>14584-865</u>		4. Project Monitor:		4c. Rotameter Number: <u>HP-120</u>	
5. Date: <u>03.03.02</u>		6. Abatement Location: <u>ENTIRE</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>Nuclepore</u> Lot # <u>98.116.617</u>		9. Type: a. ☐ Background c. ☐ Abatement b. ☐ Pre-Abate d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	
2a. Project Address: <u>100 Trinity Pl, NY, NY</u>		3a. Task #: <u>01</u>		4a. Air Sampler: <u>M. BALOTA</u>					

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CL
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
09		✓		9th floor corridor Adj. to Room # 902	09:00	12:49	229	8.0	8.0	8.0	1832		
10		✓		8th floor - Room # 804 Inside the room	09:03	12:51	228	8.0	8.0	8.0	1824		
11		✓		7th floor corridor Adj. to Room # 703	09:05	12:52	227	8.0	8.0	8.0	1816		
12		✓		6th floor - Room # 607 Inside the room	09:08	12:54	226	8.0	8.0	8.0	1808		
13		✓		5th floor corridor Adj. to Room # 504	09:10	12:56	226	8.0	8.0	8.0	1808		
14		✓		4th floor - Room # 410 Inside the room	09:13	12:58	225	8.0	8.0	8.0	1800		

CHAIN OF CUSTODY

18. Relinquished By: <u>I. Balota</u>	19. Received By: <u>John K...</u>	20. Date: <u>03-3-02</u>	21. Time: <u>7:05</u>
II			
III			

26. ATC Project Manager: <u>MARK TERJESEN</u>	27. Result To: <u>Mark Terjesen</u> Beeper/Phone #'s <u>ATC ext 266</u>
--	--

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>TEM</u>	23. Date: <u>3/4</u>	24. Time: <u>1:50</u>	25. Microscope Make/Serial #: [] Nikon Labophot 238913 [] Nikon Labophot 238917 [] Nikon Labophot 239079
a. Analyzed By: <u>CTA</u>			
b. QC By:			
c. Lab Batch #:			

28. Comments:	Analysis Methodology: PCM - NIOSH 7400A <u>TEM - AHERA</u>
---------------	--

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (10/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 18 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Push

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>	2. Project Name: <u>H.S. of Economics and Finance</u>	3. Project #: <u>14584-865</u>	4. Project Monitor:	4c. Rotameter Number: <u>HP 128</u>
5. Date: <u>03.03.02</u>	2a. Project Address: <u>100 Trinity Pl. NY, NY</u>	3a. Task #: <u>01</u>	4a. Air Sampler: <u>M. BALOTA</u>	
6. Abatement Location: <u>ENTIRE</u>	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture: Lot #:	8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture: Lot # <u>98, 116, 617</u>	9. Type: a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
15		✓		3rd floor corridor Adj. to Room # 307	09.17	13.02	225	8.0	8.0	8.0	1800.		
16			✓	Outside the building - Roof South east corner	11.18	15.07	229	8.0	8.0	8.0	1832.		
17			✓	Staircase B (open staircase) At 7th floor landing	11.21	15.09	228	8.0	8.0	8.0	1824.		
18		✓		1st floor - Lobby Adj. to Room # 102A	11.24	15.11	227	8.0	8.0	8.0	1816		
19			✓	Outside the building Adj. to Main Entrance	11.25	15.12	227	8.0	8.0	8.0	1816		
20				Valid Blank									

CHAIN OF CUSTODY

18. Relinquished By: <u>I. M. Balota</u>	19. Received By: <u>Fabrice Kull</u>	20. Date: <u>03-3-02</u>	21. Time: <u>9:05</u>
II			
III			

26. ATC Project Manager: <u>MARK Terjesen</u>	27. Result To: <u>Mark Terjesen</u> Beeper/Phone #'s <u>ATC ext 266</u>
--	---

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1182)

22. Lab Name: <u>VEIC</u>	23. Date: <u>3/8</u>	24. Time: <u>1:30</u>	25. Microscope Make/Model #: ☐ Nikon Labophot 2500LE ☐ Nikon Labophot 2500LE ☐ Nikon Labophot 2500LE
a. Analyzed By: <u>CT</u>			
b. QC By:			
c. Lab Batch #:			
28. Comments:			Analysis Methodology: PCM - NIOSH 7000A <u>TEM - AHERA</u>

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

10/1/00

CITY_21MC100_003044260