



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: <u>NYC BOE</u>		2. Project Name: <u>H.S. of Economics and Finance (M233)</u>		3. Project #: <u>14584-865</u>		4. Project Monitor: <u>—</u>		4c. Rotameter Number: <u>HP-128</u>	
5. Date: <u>03.06.02</u>		6. Abatement Location: <u>ENTIRE</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture Lot #		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>Nuclepore</u> Lot # <u>98.116.617</u>		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Other	
2a. Project Address: <u>100 Trinity Pl., NY, NY</u>		3a. Task #: <u>01</u>		4a. Air Sampler: <u>M. BALOTA</u>					

DAILY AIR SAMPLE RECORD

10. Sample ID Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Filters/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
01												
02												
03			✓	Outside the building - Roof	07.30	11.19	223	8.0	8.0	8.0	1832.	
04		✓		South east corner	07.35	11.23	228	8.0	8.0	8.0	1824.	
05			✓	8th floor - Cafeteria	07.37	11.25	228	8.0	8.0	8.0	1824	
06		✓		North west corner	07.41	11.28	227	8.0	8.0	8.0	1816	
07			✓	Staircase B (open staircase)	07.43	11.29	226	8.0	8.0	8.0	1808	
08		✓		At 7th floor landing	07.46	11.31	225	8.0	8.0	8.0	1800	
				1st floor - Auditorium								
				Left side of the entrance								
				1st floor - Lobby								
				Adj. to Room # 102A								
				Outside the building								
				Right side of the Main Entrance								

CHAIN OF CUSTODY

18. Relinquished By: <u>I. M. Balota</u>	19. Received By: <u>R. H. P.</u>	20. Date: <u>03/06/02</u>	21. Time: <u>2050</u>
II			
III			

26. ATC Project Manager: <u>Marki Teejesen</u>	27. Result To: <u>Marki Teejesen</u> Beeper/Phone #s: <u>ATC ext 266</u>
---	---

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>	23. Date: <u>3/6/02</u>	24. Time: <u>23:50</u>	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>R. H. P.</u>			
b. QC By:			
c. Lab Batch #: <u>6956</u>			
28. Comments:			Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NYC 1-100

CITY_21MC100_003044330



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 4 of 5

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name: <u>H.S. of Economics and Finance (M853)</u>		3. Project #: <u>14584-865</u>		4. Project Monitor: <u>—</u>		4c. Rotameter Number: <u>HP-128</u>	
		2a. Project Address: <u>100 Trinity Pl. NY, NY</u>		3a. Task #: <u>01</u>		4a. Air Sampler: <u>M. BALOTA</u>			
5. Date: <u>03.06.02</u>		6. Abatement Location: <u>ENTIRE</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>Nucaporic</u> Lot # <u>22.116.617</u>		9. Type: a. ☐ Background c. ☐ Abatement b. ☐ Pre-Abate d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
09			✓	Outside the building - Roof South east corner	11.19	15.09	230	8.0	8.0	8.0	1840		
10			✓	Staircase B (open staircase) At 7th floor landing	11.25	15.14	229	8.0	8.0	8.0	1832		
11		✓		1st floor - Lobby Adj. to Room # 102A	11.29	15.17	228	8.0	8.0	8.0	1824		
12			✓	Outside the building Right side of Main Entrance	11.31	15.18	227	8.0	8.0	8.0	1816		
13		✓		9th floor - hallway Adj. to Room # 904	15.26	19.16	230	8.0	8.0	8.0	1840		
14		✓		8th floor - Room # 804 Inside the room	15.28	19.18	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By: <u>M. Balota</u>		19. Received By: <u>Rhoj</u>		20. Date: <u>03/06/02</u>	21. Time: <u>12:50</u>
II					
III					
26. ATC Project Manager: <u>Mark Teyesen</u>		27. Result To: _____ Beeper/Phone #'s _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>		23. Date: <u>3/6/02</u>	24. Time: <u>23:50</u>
a. Analyzed By: <u>Rhoj</u>			
b. QC By: _____			
c. Lab Batch #: <u>6956</u>			
28. Comments: _____			
25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079			
Analysis Methodology PCM - NIOSH 7400A TEM - AHERA			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

 Page 3 of 3
TURNAROUND TIME
☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush
PROJECT INFORMATION

1. Client: <u>NYC BOE</u>		2. Project Name: <u>H.S. of Economics and Finance (M833)</u>		3. Project #: <u>14584-865</u>		4. Project Monitor: <u>—</u>		4c. Rotameter Number: <u>HP-128</u>	
5. Date: <u>03.06.02</u>		6. Abatement Location: <u>ENTIRE</u>		2a. Project Address: <u>100 Trinity Pl. NY, NY</u>		3a. Task #: <u>01</u>		4a. Air Sampler: <u>M. BALOTA</u>	
7. ☐ PCM (0.8 micron MCF)		8. ☒ TEM (0.45 micron MCF)		9. Type:		c. ☐ Abatement		1. ☐ Environmental	
Cassette/Filter Manufacture: <u>—</u>		Cassette/Filter Manufacture: <u>Nuclepore</u>		a. ☐ Background		d. ☐ Post-Abate		g. ☒ Ambient	
Lot #: <u>—</u>		Lot #: <u>98.116.617</u>		b. ☐ Pre-Abate		e. ☐ OSHA		h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
15		V		7th floor - Corridor Next to Boy's Bathroom	15.30	19.20	230	8.0	8.0	8.0	1840		
16		V		6th floor - Room # 608 Inside the room	15.35	19.24	229	8.0	8.0	8.0	1832		
17		V		5th floor - Corridor Adj. to Room # 503	15.42	19.29	227	8.0	8.0	8.0	1816		
18		V		4th floor - Room # 408 Inside the room	15.44	19.30	226	8.0	8.0	8.0	1808.		
19		V		3rd floor - Corridor Across Room # 309	15.46	19.32	226	8.0	8.0	8.0	1808.		
20				Male Blank									

CHAIN OF CUSTODY

18. Relinquished By: <u>M. Balota</u>		19. Received By: <u>Mark Teyesen</u>		20. Date: <u>7/16/02</u>	21. Time: <u>2050</u>
26. ATC Project Manager: <u>Mark Teyesen</u>		27. Result To: <u>Mark Teyesen</u> Beeper/Phone #'s <u>ATC Ext 266</u>			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>		23. Date:	24. Time:	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>RKug</u>		<u>3/6/02</u>	<u>23:50</u>	
b. QC By:				
c. Lab Batch #: <u>6956</u>				
28. Comments:				Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA

WHITE File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY 1 (100)

CITY_21MC100_003044332