

ATC ASSOCIATES INC.

BATCH NO.

19836

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE		2. Project Name: AHERA REINSPECTION		3. Project # 14584-0819		4. Project Manager: ANDREAS ANDREOU	
		2a. Project Address: 201 Warren Street, New York, NY 10282				4a. Investigator: Yiannis Efsthliou	
5. Date: <u>12/11/01</u>		6. Building Name: P.S. 89M		8. Turnaround Time: ☐ STAT ☐ 24 HRS ☐ 72 HRS ☒ OTHER <u>RUSH</u>		9. Comments (Field): Analyzed all them for asbestos	
		7. Sampling Areas: Entire		☐ 6 HRS ☐ 48 HOURS ☐ NORMAL		10. Time in / Time out:	

H.A.#	SAMPLE ID NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR NUMBER	RESULTS
	PS89M - 12/11-01	Settled Dust	CLASSROOM #504, EAST SIDE UNIT VENT FROM THE FILTER		ND
	PS89M - 12/11-02	Settled Dust	_____		ND
	PS89M - 12/11-03	Settled Dust	CLASSROOM #504, EAST SIDE UNIT VENT FROM THE FLOOR		TR CHR
	PS89M - 12/11-04	Settled Dust	CLASSROOM #526, North side Unit Vent From the Filter		ND
	PS89M - 12/11-05	Settled Dust	_____		TR CHR
	PS89M - 12/11-06	Settled Dust	CLASSROOM #526, North side Unit Vent From the floor		ND

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time:	20. Received By:	21. Date:	22. Time:	23. Method of Submittal:
<u>Yiannis Efsthliou</u>	<u>12/11/01</u>	<u>13:30</u>	<u>Stacey</u>	<u>12/11/01</u>	<u>13:30</u>	FIELD
						WALK IN
						US MAIL
						FED-X
						OTHER

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:	27. Comments (Lab):
<u>E. A. Charter</u>	<u>12/11/01</u>	<u>PM</u>	<u>6 PM < 6 Hr.</u>
24a. Analyzed By:			
24b. Analyzed By:			
24c. QC By:			