

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-19-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Snyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217-29881

SAMPLED BY: Client

SAMPLE DATE: 08-17-02
DATE RECEIVED: 08-17-02
DATE ANALYZED: 08-17-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION (µg/ft ²)	DETECTION LIMIT (µg/ft ²)
LW-31	21251	Rm 373 Floor North Side by Radiator	<9.0	9.0
LW-32	21251	Rm 373 Table Top North Side	<9.0	9.0
LW-33	21251	Rm 372 Floor Center of Room	<9.0	9.0
LW-34	21251	Rm 372 Desk Top South Desk	<9.0	9.0
LW-35	21251	Rm 371 Floor North Side by Blackboard	<9.0	9.0
LW-36	21251	Rm 371 Table Top North East Side	<9.0	9.0
LW-37	21251	Rm 371A Floor 3' of Entrance	<9.0	9.0
LW-38	21251	Rm 371A Desk Top 1st Desk	<9.0	9.0
LW-39	21251	Rm 371B Floor of Room Ent.	<9.0	9.0
LW-40	21251	Rm 371B Top of 1st Desk	<9.0	9.0
LW-41	21251	Rm 371C Floor Center of Room	13.8	9.0
LW-42	21251	Rm 371C Top of Bed	18.7	9.0
LW-43	21251	Bedroom 371D Floor by Entrance	<9.0	9.0

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel 212-353-8280
Fax 212-353-8306

LW-44	21251	Rm 371D Top of Bedroom Platform	<9.0	9.0
LW-45	21251	Rm 371E Floor NW Side	26.8	9.0
LW-46	21251	Rm 371E Top of Refrigerator South	<9.0	9.0
LW-47	21251	Rm 371F Floor 3' of Entrance	<9.0	9.0
LW-48	21251	Rm 371G Floor 3' of Entrance	<9.0	9.0
LW-49	21251	NE Corridor O/S GYM Floor by North Entrance	<9.0	9.0
LW-50	21251	GYM (G380) Floor Center of GYM	<9.0	9.0
LW-51	21251	GYM (G380) Top of Bleachers South End	13.2	9.0
LW-52	21251	G380B Floor Center of Room	11.4	9.0
LW-53	21251	G380 Shelf Top Left Side	<9.0	9.0
LW-54	21251	G380C Floor West Side	15.5	9.0
LW-55	21251	G380C Shelf Center	<9.0	9.0
LW-56	21251	G382 (Aux. GYM) Floor by G382B	<9.0	9.0
LW-57	21251	G382 Top of Tumbling Pads	23.4	9.0
LW-58	21251	G382A Floor by Entrance	26.0	9.0
LW-59	21251	G382B Floor Center of Room	27.9	9.0
LW-60	21251	G382B Shelf Left Side	30.8	9.0
LW-61	21251	Rm 317 Floor 3' of Entrance	19.2	9.0
LW-62	21251	Rm 317 Shelf Right Side	<9.0	9.0
LW-63	21251	Corridor East Side by Elevator Floor	<9.0	9.0
LW-64	21251	Locker #3-98 O/S GYM	<9.0	9.0
FBL-1	21251	Field Blank	<9.0 µg	9.0 µg
FBL-2	21251	Field Blank	<9.0 µg	9.0 µg
FBL-3	21251	Field Blank	<9.0 µg	9.0 µg
FBL-4	21251	Field Blank	<9.0 µg	9.0 µg

NOTE 1:

THE REPORTING LIMIT (RL) IS 18.0 µg

NOTE 2:

HUD Guidelines for final clearance dust wipe samples: Floor 40 µg/ft², Window sills 250 µg/ft², Window wells 400 µg/ft², Exterior surfaces 800 µg/ft².

NOTE 3:

Blank units are in µg

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: _____

TCM

REPORT PREPARED BY: _____

[Signature]

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

[Signature]

LABORATORY DIRECTOR: _____

[Signature]

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).