

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

#21155

89184

516-358-2955

Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA		CONTACT: Hamid Savoj		SAMPLER (SIGNATURE) [Signature]		DATE 8/14/02		TIME		SAMPLE(S) SEALED ☒ YES ☐ NO	
PROJECT LOCATION: Stuyvesant HS 345 Chambers St NY		PROJECT # M477-15217-29881		SAMPLER NAME (PRINT) Kirk McKenzie						CORRECT CONTAINER(S) ☒ YES ☐ NO	
SAMPLE INFORMATION:				MATRIX (CIRCLE ONE): ☒ WIPE ☐ PAINT ☐ SOIL ☐ OTHER							
LABORATORY #	SAMPLE #	LOCATION	AREA (FT ²)	SURFACE MATERIAL				LAB RESULT			
				WOOD	METAL	BRICK	OTHER				
	LW-26	ROOM 428 - FLOOR center of room	1				X	6 hr C9.0			
	LW-27	ROOM 438 - Shelf EAST side of room	1		X			C9.0			
	LW-28	ROOM 438A - FLOOR center of room	1				X	C9.0			
	LW-29	ROOM 438A - Table Top EAST side of room	1				X	C9.0			
	LW-30	ROOM 436 - FLOOR 3' of WEST ENTRANCE	1				X	C9.0			
	LW-31	ROOM 436 - Table Top Printer Table - west side	1				X	C9.0			
	LW-32	ROOM 424 - FLOOR 2' of ENTRANCE	1				X	C9.0			
	LW-33	ROOM 432 - FLOOR center of room	1				X	C9.0			
TURNAROUND REQUIRED:				COMMENTS / INSTRUCTIONS							
NORMAL ☐ STAT ☐ BY 1/1				6 HR - TAT							
RELINQUISHED BY (SIGNATURE) [Signature]		DATE 8/14/02 TIME 2:30		PRINTED NAME Kirk McKenzie		RECEIVED BY (SIGNATURE) [Signature]		DATE 8/15		PRINTED NAME	
RELINQUISHED BY (SIGNATURE) Gr. Putalov		DATE 8/15/02 TIME 4:50		PRINTED NAME Gr. Putalov		RECEIVED BY LAB (SIGNATURE) R. Droudika		DATE 8/15 TIME 4:50		PRINTED NAME R. Droudika	

CITY_21MC100_003049512

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

#21155 P9 284

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS N7C SCA		CONTACT: HAMID SAADI		SAMPLER(S) SIGNATURE [Signature]		DATE 8/14/02		TIME		SAMPLE(S) SEALED (YES) NO	
PROJECT LOCATION: Stuyvesant H.S.		PROJECT # M477-15217-29881		SAMPLER NAME (PRINT) LITTLE McLenzie						CORRECT CONTAINER(S) (YES) NO	
PROJECT LOCATION: 345 Chambers St. N.Y.				MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER _____							
SAMPLE INFORMATION:				AREA (FT ²)		SURFACE MATERIAL				LAB RESULT	
LABORATORY #	SAMPLE #	LOCATION				WOOD	METAL	BRICK	OTHER		
	LW-34	ROOM 430 - FLOOR 3' of ENTRANCE		1					X	29/12 C9.0	
	LW-35	ROOM C428 - FLOOR Center		1					X	C9.0	
	LW-36	CORRIDOR O/S RM 438 - FLOOR		1					X	C9.0	
	LW-37	ROOM 446 - FLOOR 4' of ENTRANCE		1					X	C9.0	
	LW-38	ROOM 448 - FLOOR 4' of ENTRANCE		1					X	C9.0	
	LW-39	Locker #4-235 O/S RM 438 A		1			X			C9.0	
	LW-40	ROOM 453 - FLOOR 2' of adjacent		1					X	C9.0	
	LW-41	ROOM 453 - Top of SE work table		1					X	C9.0	
				TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 1/1					COMMENTS / INSTRUCTIONS 6 HR TAT		
RELINQUISHED BY (SIGNATURE) [Signature]		DATE 8/14/02 TIME 2:30		PRINTED NAME LITTLE McLenzie		RECEIVED BY (SIGNATURE) [Signature]		DATE		PRINTED NAME	
RELINQUISHED BY (SIGNATURE) Gr. Mularo		DATE 8/15/02 TIME 4:50		PRINTED NAME GREGORY Mularo		RECEIVED BY LAB (SIGNATURE) R. D. Mularo		DATE 8/15 TIME 4:50		PRINTED NAME R. D. Mularo	

CITY_21MC100_003049513

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

#21155

3.84

516-358-2955

Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA		CONTACT: HAMID SAJJ		SAMPLER (SIGNATURE) <i>[Signature]</i> DATE 8/14/02 TIME		SAMPLE(S) SEALED (YES) NO		
PROJECT LOCATION: Stuyvesant H.S. 345 Chambers ST NY		PROJECT # M477-15217-29881		SAMPLER NAME (PRINT) Kirk McKenzie		CORRECT CONTAINER(S) (YES) NO		
SAMPLE INFORMATION:				MATRIX (CIRCLE ONE): (WIPE) PAINT SOIL OTHER				
LABORATORY #	SAMPLE #	LOCATION	AREA (FT ²)	SURFACE MATERIAL				LAB RESULT
				WOOD	METAL	BRICK	OTHER	
	LW-42	ROOM 452 - Floor center of room	1				X	CG.0
	LW-43	ROOM 452 - Shelf Top Right side of room	1		X			CG.0
	LW-44	ROOM 451 - Floor 7' of entrance	1				X	CG.0
	LW-45	ROOM 451 - Top of East Printer Table	1				X	CG.0
	LW-46	ROOM 450 - Floor 3' of East window	1				X	CG.0
	LW-47	ROOM 450 - Table Top Computer Table at center wall	1				X	CG.0
	LW-48	ROOM 450A CORRIDOR, 10' of west side Escalator - Floor	1				X	CG.0
	LW-49	Locker #4414 at corridor w/o escalator	1		X			CG.0
				TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY 1/1			COMMENTS / INSTRUCTIONS 6 H2 TIT	
RELINQUISHED BY (SIGNATURE) <i>[Signature]</i>		DATE 8/14/02 TIME 2:00	PRINTED NAME Kirk McKenzie		RECEIVED BY (SIGNATURE) <i>[Signature]</i>		DATE TIME	PRINTED NAME
RELINQUISHED BY (SIGNATURE) G. Pulato		DATE 8/15/02 TIME 4:50	PRINTED NAME Gregory Pulato		RECEIVED BY LAB (SIGNATURE) R. Dondina		DATE 8/15 TIME 4:50	PRINTED NAME R. Dondina

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_003049514

TAYLOR ENVIRONMENTAL GROUP, INC.
130 JERICHO TPKE., FLORAL PARK, NY 11001

#21155

516-358-2955
Fax 516-358-1780

LEAD SAMPLING DATA AND CHAIN OF CUSTODY DOCUMENT

CLIENT NAME/ADDRESS NYC SCA		CONTACT: HAMID SAADI		SAMPLER (SIGNATURE) <i>[Signature]</i>		DATE 8/14/02		TIME		SAMPLE(S) SEALED ☒ YES ☐ NO	
PROJECT LOCATION: Stuyvesant HS 345 Chambers Street		PROJECT # M477-15217-29881		SAMPLER NAME (PRINT) Lirk McKenzie						CORRECT CONTAINER(S) ☒ YES ☐ NO	
SAMPLE INFORMATION:				MATRIX (CIRCLE ONE): ☒ WIFE ☐ PAINT ☐ SOIL ☐ OTHER							
LABORATORY #	SAMPLE #	LOCATION	AREA (FT ²)	SURFACE MATERIAL				LAB RESULT			
				WOOD	METAL	BRICK	OTHER				
	LW-50	Corridor o/s Rm 403 FLOOR	1				X	< 9.0			
	FBL-1 FBL-1	Field Blank						< 9.0			
	FBL-2 FBL-2	Field Blank						< 9.0			
	FBL-3 FBL-3	Field Blank						< 9.0			
				TURNAROUND REQUIRED: NORMAL ☐ STAT ☐ BY / /				COMMENTS / INSTRUCTIONS 8 HR TAT			
RELINQUISHED BY (SIGNATURE) <i>[Signature]</i>		DATE 8/14/02 TIME 2:00		PRINTED NAME Lirk McKenzie		RECEIVED BY (SIGNATURE) <i>[Signature]</i>		DATE		PRINTED NAME	
RELINQUISHED BY (SIGNATURE) Gr. Pulata		DATE 8-15-02 TIME 4:50		PRINTED NAME Gregory Pulata		RECEIVED BY LAB (SIGNATURE) R. Droudina		DATE 8.15 TIME 4.50		PRINTED NAME R. Droudina	

WHITE - OFFICE / YELLOW - LAB / PINK - CLIENT

CITY_21MC100_003049515