

EMSL Analytical, Inc.

208 Stone Hinge Lane, Carle Place, NY 11514

Phone: 516-997-7251 Fax: 516-997-7528 Email: carleplacelab@emsl.com

EMSL

Attn: Taylor Environmental Group, Inc.
 Floral Park Corporate Center
 130 Jericho Tpke.
 Floral Park, NY 11001

Fax: (516) 358-1780 Phone: 516-358-2955

Project: SCA STUYVESANT HS, 345 CHAMBERS ST, M477-
 15217/29881

Customer ID: TAYL50
 Customer PO:
 Received: 08/22/02 6:53 PM

EMSL Order: 060208639
 EMSL Project ID:

Analysis Date 8/23/2002

Asbestos Analysis of Non-Friable Organically Bound Materials by PLM via the NY State ELAP 198.1 Method

SAMPLE ID	DESCRIPTION	APPEARANCE	% MATRIX MATERIAL	% NON-ASBESTOS FIBERS	ASBESTOS TYPES	% TOTAL ASBESTOS
1A 060208639-0001	1ST FL AUDITOR./THEATE R BEHIND SEAT,A- 2 CARPET	Tan Non-Fibrous Homogeneous	100.0	None	Inconclusive: No Asbestos Detected	
2A 060208639-0002	1ST FL AUDITOR./THEATE R BEHIND SEAT,A- 1 CARPET	Tan Non-Fibrous Homogeneous	100.0	None	Inconclusive: No Asbestos Detected	
3A 060208639-0003	1ST FL AUDITOR./THEATE R BEHIND SEAT,E- 118 CARPET	Tan Non-Fibrous Homogeneous	100.0	None	Inconclusive: No Asbestos Detected	

Syreeta Robinson

Analyst



Michelle McGowan
 or other approved signatory

Polarized Light Microscopy is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos containing. The above report relates only to the material tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used to claim product endorsement by NVLAP nor any agency of the United States Government.

NYSP10B2

1