NYC 9/11 Public Portal Document

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD — PAGE 1 OF 1

TECHNICIAN: Carlos Jont	CLIENT: NYCSCA.	SITE ADDRESS: Stuyvesant H.S.	DATE SUBMITTED: 8-20-02
DATE SAMPLED: 8-20-02	CONTACT: Hamid Saadat	WORK AREA: 4th Floor	DATE LOGGED:
ROTOMETER NO.: TOG L-16.	PROJECT NO.: M477-13217-29881	PROJECT MANAGER: C. McClown.	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	F/CC
4-L1		IWA ☐ OWA ☐ 4th Fl Corridor @ Room 440	4/4	1031	1519	288	4	1152			<1.3	
4-L2		IWA ☐ OWA ☐ Room 450 - Robotics - Center	4/4	1033	1520	287	4	1148			<1.3	
4-L3		IWA ☐ OWA ☐ 4th Fl Corridor @ Top of Esc + West Stair	4/4	1036	1521	286	4	1144			<1.3	
4-L4		IWA ☐ OWA ☐ Room 411 - Computer Rm	4/4	1039	1522	283	4	1132			<1.3	
4-L5		IWA ☐ OWA ☐ 4th Fl Corridor @ East Stair + Rm 401/402	4/4	1042	1523	271	4	1084			<1.4	
FB-1		IWA ☐ OWA ☐ F/Blank-1								no filter		
FB-2		IWA ☐ OWA ☐ F/Blank-2									<1.5	
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

RELINQUISHED TO TEG DROP BOX (SIGNATURE): John Melonas	DATE: 8/20/02	TIME: 1620	RECEIVED FROM TEG DROP BOX (SIGNATURE): Alice 8/20 Gym	DATE:	TIME:
RELINQUISHED BY: (SIGNATURE)	DATE:	TIME:	RECEIVED BY: (SIGNATURE) ATC E.A.C.	DATE: 8/21/02	TIME: 1620
ANALYST: (SIGNATURE): M Li	DATE: 8/20/02	TIME: 900 PM	COMMENTS: OHEARN NIOSH 7082		

CIRCLE: PCM TEM — BGRD PRE DURING POST — OSHA — OTHER Lonty

LOT: FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

CITY_21MC100_011273987

NYC-WTC_000200140

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-21-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
4th Floor

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE 08-20-02
DATE RECEIVED: 08-20-02
DATE ANALYZED: 08-20-02

SAMPLE MEDIA: Air Samples
ANALYSIS REQUIRED: Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
4-L1	21336	4th Floor Corridor @ Rm 440	<1.3	1.3
4-L2	21336	Rm 450 Robotics Conyer	<1.3	1.3
4-L3	21336	4th Floor Corridor @ Top of Esc. West Stair	<1.3	1.3
4-L4	21336	Rm 411 Computer Rm	<1.3	1.3
4-L5	21336	4th Floor Corridor @ East Stair Rm 401/402	<1.4	1.4
FB1	21336	Field Blank - NO FILTER	-	-
FB2	21336	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

NYC-WTC_000200141

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: TCH

REPORT PREPARED BY: _____

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: _____

LABORATORY DIRECTOR: _____

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000200142