

TAYLOR ENVIRONMENTAL GROUP

DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN <i>W. Plonk</i>		CLIENT <i>NYC SCH</i>	SITE ADDRESS <i>SHUYOESANT HS. CHAMBERS ST, NY, NY</i>				DATE SUBMITTED <i>8/23/02</i>					
DATE SAMPLED <i>AUGUST 23, 2002</i>		CONTACT <i>LAUREN SIVOS</i>	WORK AREA <i>7TH FLOOR</i>				DATE LOGGED					
ROTMETER NO. <i>L-18</i>		PROJECT NO. <i>M477-15217-29887</i>	PROJECT MANAGER <i>G. TAYLOR</i>				DATE APPROVED / SIGNATURE					

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVER-AGE)	LITERS	FIELDS	FIBERS	F/MM ²	F/CC
7-L1		IWA ☒ eastern end of corridor by rm 707 OWA ☐	4/4	3 ¹⁵	0815	298	4	1192				
7-L2		IWA ☒ center of corridor by rm C721 OWA ☐	4/4	3 ²³	0816	283	4	1132				
7-L3		IWA ☒ west end corridor by rm 737 OWA ☐	4/4	3 ²⁵	0817	292	4	1168				
FB-1		IWA ☐ F/BANK-1 OWA ☐	/									
FB-2		IWA ☐ F/BANK-2 OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									
		IWA ☐ OWA ☐	/									

RELINQUISHED TO TEG DROP BOX (SIGNATURE) <i>[Signature]</i>	DATE <i>8/23/02</i>	TIME <i>0930</i>	RECEIVED FROM TEG DROP BOX (SIGNATURE) <i>[Signature]</i>	DATE <i>8/27/02</i>	TIME <i>9:30</i>	CIRCLE PCM TEM BGRD PRE DURING POST OSHA OTHER <i>[Signature]</i>
RELINQUISHED BY: (SIGNATURE)	DATE	TIME	RECEIVED BY: (SIGNATURE)	DATE	TIME	
ANALYST: (SIGNATURE) <i>[Signature]</i>	DATE <i>8-23-02</i>	TIME <i>1145am</i>	COMMENTS <i>[Signature]</i>			

WHITE: Office Copy

YELLOW: Lab Copy

PINK: Samples

ORANGE: Site Copy

[Signature]

CITY_21MC100_011274046

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-23-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
7th Floor

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 08-23-02
DATE RECEIVED: 08-23-02
DATE ANALYZED: 08-23-02

SAMPLE MEDIA: Air Samples
ANALYSIS REQUIRED: Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu\text{g}/\text{m}^3$)	DETECTION LIMIT ($\mu\text{g}/\text{m}^3$)
7-L1	21418	Eastern End of Corridor by Rm 707	<1.3	1.3
7-L2	21418	Center of Corridor by Rm C721	<1.3	1.3
7-L3	21418	West End Corridor by Rm 737	<1.3	1.3
FB1	21418	Field Blank	<1.5 μg	1.5 μg
FB2	21418	Field Blank	<1.5 μg	1.5 μg

NOTE 1:**THE REPORTING LIMIT (RL) IS 3.0 μg** **NOTE 2:**At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu\text{g}/\text{m}^3$ and a permissible exposure level (PEL) of 50 $\mu\text{g}/\text{m}^3$ for personal samples.**NOTE 3:**Blank units are in μg

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: IL

REPORT PREPARED BY: [Signature]

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR: [Signature]

LABORATORY DIRECTOR: [Signature]

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).