

ATC ASSOCIATES INC.

BATCH NO.

20186

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Name: AHERA REINSPECTION	3. Project #: 14584-C819	4. Project Manager: Yiannis Efsthathiou
2a. Project Address: 201 Wearren street, New York, NY 10282			4a. Investigator: Mariana Medinets
5. Date: 3-22-02	6. Building Name: P.S. 89M	8. Turnaround Time: ☒ STAT ☐ 24 HRS ☐ 72 HRS ☐ OTHER ☐ 6 HRS ☐ 48 HOURS ☐ NORMAL	9. Comments (Field): Analyzed all of them for fiberglass
7. Sampling Areas:			10. Time in / Time out:

H.A.#	SAMPLE ID NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR NUMBER	RESULTS
01	PS89M-3/22/02- Fiberglass-	Settled Dust	outside of school ground concr. surface	North side Entrance	ND
02	PS89M-3/22/02- Fiberglass-	Settled Dust	↓	South side Entrance	ND
03	PS89M-3/22/02- Fiberglass-	Settled Dust	Playground Ground concr. surf.	Center	ND
04	PS89M-3/22/02- Fiberglass-	Settled Dust		South side	ND
05	PS89M-3/22/02- Fiberglass-	Settled Dust		North side	ND
06	PS89M-3/22/02- Fiberglass-	Settled Dust		East side	ND
07	PS89M-3/22/02- Fiberglass-	Settled Dust	↓	West side	ND
08	PS89M-3/22/02- Fiberglass-	Settled Dust	Cafeteria floor		N/A
09	PS89M-3/22/02- Fiberglass-	Settled Dust	1st. fl. Hallway fl. South of Cafeter		N/A
10	PS89M-3/22/02- Fiberglass-	Settled Dust	↓ East of Cafeter		N/A

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time:	20. Received By:	21. Date:	22. Time:	23. Method of Submittal:
U. Medinets	3-22-02		Y. Efsthathiou	3/22/2	2:30 PM	FIELD
						WALK IN
						US MAIL
						FED-X
						OTHER

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:	27. Comments (Lab):
Yolene P. Pappas	3/22/2	PM	40 Plus < 6
24a. Analyzed By:			
24b. Analyzed By:			
24c. QC By:			

ATC ASSOCIATES INC.

BATCH NO.

20186

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Name: AHERA REINSPECTION	3. Project # 14584-0819	4. Project Manager: Yiannis Efsthathiou
2a. Project Address: 201 Warren street, New York, NY 10282			4a. Investigator: Mariana Medinets
5. Date: 3-22-02	6. Building Name: P.S. 89M	8. Turnaround Time: ☐ STAT ☐ 24 HRS ☐ 72 HRS ☐ OTHER ☐ 6 HRS ☐ 48 HOURS ☐ NORMAL	9. Comments (Field): Analyzed all of them for fiberglass 10. Time in / Time out:
7. Sampling Areas:			

H.A.#	SAMPLE ID NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR NUMBER	RESULTS
11	PS89M-3/22/02- Fiberglass-	Settled Dust	2nd fl. Hallway South side		ND
12	PS89M-3/22/02- Fiberglass-	Settled Dust	Auditorium		ND
13	PS89M-3/22/02- Fiberglass-	Settled Dust	Gym floor		ND
14	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 304 floor		ND
15	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 402 floor		ND
16	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 328 floor		ND
17	PS89M-3/22/02- Fiberglass-	Settled Dust	4th fl. Hallway South side		ND
18	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 201 floor		ND
19	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 202 floor		ND
20	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 204 floor		ND

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time:	20. Received By:	21. Date:	22. Time:	23. Method of Submittal:
U. Medinets	3-22-02		Rege	3/22/2	2:30pm	FIELD
						WALK IN
						US MAIL
						FED-X
						OTHER

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:	27. Comments (Lab):
24a. Analyzed By: Y. Rejzgarlar	3/22/2	pm	
24b. Analyzed By:			
24c. QC By:			

ATC ASSOCIATES INC.

BATCH NO.

20126

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE	2. Project Name: AHERA REINSPECTION	3. Project # 14584-0819	4. Project Manager: Yiannis Efsthathiou
	2a. Project Address: 201 Wearren street, New York, NY 10282		4a. Investigator: Mariana Medinets
5. Date: <u>3-22-02</u>	6. Building Name: P.S. 89M	8. Turnaround Time: ☒ STAT ☐ 24 HRS ☐ 72 HRS ☐ OTHER ☐ 6 HRS ☐ 48 HOURS ☐ NORMAL	9. Comments (Field): Analyzed all of them for fiberglass 10. Time in / Time out:
7. Sampling Areas:			

H.A.#	SAMPLE ID NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR NUMBER	RESULTS
21	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 504 floor		ND
22	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 226 floor		ND
23	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 232 floor		ND
24	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 230 floor		ND
25	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 219 floor		ND
26	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 302 floor		ND
27	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 301 floor		ND
28	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 316 floor		ND
29	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 308 floor		ND
30	PS89M-3/22/02- Fiberglass-	Settled Dust	R. 326 floor		ND

CHAIN OF CUSTODY

17. Relinquished By: <u>M. Medinets</u>	18. Date: <u>3-22-02</u>	19. Time:	20. Received By: <u>Y. Efsthathiou</u>	21. Date: <u>3/22/2</u>	22. Time: <u>2:30 PM</u>	23. Method of Submittal: FIELD WALK IN US MAIL FED-X OTHER

LAB INFORMATION

24. Name and Signature: <u>Y. Efsthathiou</u>	25. Date: <u>3/22/2</u>	26. Time: <u>pm</u>	27. Comments (Lab):
24a. Analyzed By:			
24b. Analyzed By:			
24c. QC By:			

ATC ASSOCIATES INC.

BATCH NO:

20186

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client: NYC - BOE		2. Project Name: AHERA REINSPECTION		3. Project #: 4584-0819		4. Project Manager: Yiannis Efstathiou	
		2a. Project Address: 201 Weyan street, New York, NY 10282				4a. Investigator: Mariana Medinets	
5. Date: <u>3-22-02</u>		6. Building Name: P.S. 89M		8. Turnaround Time: ☒ STAT ☐ 24 HRS ☐ 72 HRS ☐ OTHER ☐ 6 HRS ☐ 48 HOURS ☐ NORMAL		9. Comments (Field): Analyzed all of them for fiberglass	
		7. Sampling Areas:				10. Time in / Time out:	

H.A.#	SAMPLE ID NUMBER	MATERIAL DESCRIPTION	LOCATION	FLOOR NUMBER	RESULTS
<u>31</u>	PS89M-3/22/02- Fiberglass-	Settled Dust	<u>R. 401</u> <u>floor</u>		<u>ND</u>
<u>32</u>	PS89M-3/22/02- Fiberglass-	Settled Dust	<u>R. 404</u> <u>floor</u>		<u>ND</u>
<u>33</u>	PS89M-3/22/02- Fiberglass-	Settled Dust	<u>R. 408</u> <u>floor</u>		<u>ND</u>
<u>34</u>	PS89M-3/22/02- Fiberglass-	Settled Dust	<u>R. 426</u> <u>floor</u>		<u>ND</u>
<u>35</u>	PS89M-3/22/02- Fiberglass-	Settled Dust	<u>R. 428</u> <u>floor</u>		<u>ND</u>
<u>36</u>	PS89M-3/22/02- Fiberglass-	Settled Dust	<u>R. 512</u> <u>floor</u>		<u>ND</u>
<u>37</u>	PS89M-3/22/02- Fiberglass-	Settled Dust	<u>R. 506</u> <u>floor</u>		<u>ND</u>
<u>38</u>	PS89M-3/22/02- Fiberglass-	Settled Dust	<u>R. 526</u> <u>floor</u>		<u>ND</u>
<u>39</u>	PS89M-3/22/02- Fiberglass-	Settled Dust	<u>R. 528</u> <u>floor</u>		<u>ND</u>
<u>40</u>	PS89M-3/22/02- Fiberglass-	Settled Dust	<u>R. 532</u> <u>floor</u>		<u>ND</u>

CHAIN OF CUSTODY

17. Relinquished By:	18. Date:	19. Time:	20. Received By:	21. Date:	22. Time:	23. Method of Submittal:
<u>W. Keddick</u>	<u>3-22-02</u>		<u>Y. Efstathiou</u>	<u>3/22/2</u>	<u>3:30p</u>	FIELD
						WALK IN
						US MAIL
						FED-X
						OTHER

LAB INFORMATION

24. Name and Signature:	25. Date:	26. Time:	27. Comments (Lab):
24a. Analyzed By: <u>Y. Efstathiou</u>	<u>3/22/2</u>	<u>pm</u>	
24b. Analyzed By:			
24c. QC By:			