



AIR MONITORING DATA AND

CHAIN OF CUSTODY FORM

Page I of III

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: NYC BOE 2. Project Name: P.S. 89M 77672 3. Project #: 14584 4. Project Monitor: DANIEL ROY Finkley 4c. Rotameter Number: HP 185

2a. Project Address: 801 WARREN ST 3a. Task #: _____ 4a. Air Sampler: DANIEL ROY Finkley

5. Date: TUES 3/5/02 6. Abatement Location: ALL FLOORS, PLAYGROUND + ROOF. 7. ☒ PCM (0.8 micron MCE) 8. ☒ TEM (0.45 micron MCE) 9. Type: c. ☐ Abatement f. ☐ Environmental

Cassette/Filter Manufacture: _____ Cassette/Filter Manufacture: MULTI METRICS a. ☐ Background d. ☐ Post-Abate g. ☒ Ambient

Lot #: _____ Lot #: 00263916 b. ☐ Pre-Abate e. ☐ OSHA h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg		
17				Field Blank <u>CLOSED.</u>								
01		IN		Field Blank <u>cafe/teria</u>	7:20	11:10 ^{AM}	230	8.0	8.0	8.0	1840	
02		SIDE		<u>ON STANDS.</u>	7:23	11:13	230	8.0	8.0	8.0	1840	
03		OUT		<u>1st floor hallway outside of cafe/teria.</u>	7:26	11:16	230	8.0	8.0	8.0	1840	
04		SIDE		<u>PLAYGROUND NORTH END COLUMN NEXT TO BENCH</u>	7:29	11:19	230	8.0	8.0	8.0	1840	
05		IN		<u>PLAYGROUND SOUTH END COLUMN NEXT TO BENCH</u>	7:40	11:30	230	8.0	8.0	8.0	1840	
06		OUT		<u>2ND floor AUDITORIUM</u>	7:42	11:32	230	8.0	8.0	8.0	1840	
				<u>4th floor 3rd floor GYMNASIUM</u>								

CHAIN OF CUSTODY

18. Relinquished By: [Signature] 19. Received By: [Signature] 20. Date: 03/05/02 21. Time: 20:00

26. ATC Project Manager: Andreas Andreadou 27. Result To: A Andreadou Beeper/Phone #'s: 646-772-1153

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: TECO 23. Date: 3/5/02 24. Time: 10:00 25. Microscope Make/Serial #: _____

a. Analyzed By: [Signature] b. QC By: _____ c. Lab Batch #: 6939

26. Comments: _____

Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1-03)

CITY_21MC100_011275838



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page II of II

TURNAROUND TIME

- ☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: NYC BOE	2. Project Name: P-5 89M	3. Project #: 14584-0819	4. Project Monitor: DANIEL ROY FUNKLEY	4c. Rotameter Number: HP 125
5. Date: 8/5/02	2a. Project Address: 201 WARREN ST	3a. Task #:	4a. Air Sampler:	
6. Abatement Location: ALL FLOORS, PLAYGROUND + ROOF	7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: _____ Lot #: _____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture: MULTI METRICS Lot #: _____	9. Type: a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
018				Field Blank									
				Field Blank									
07			OUT SIDE	ROOF - CENTRAL AREA	0735 AM	1125 AM	230	8.0	8.0	8.0	1840		
08			IN SIDE	1ST FLOOR - HALLWAY OUTSIDE CAFETERIA	1113 AM	303 PM	230	8.0	8.0	8.0	1840		
09			OUT SIDE	PLAYGROUND - NORTH END COLUMN NEXT TO BENCH	1116 AM	306 PM	230	8.0	8.0	8.0	1840		
010				PLAYGROUND - SOUTH END COLUMN NEXT TO BENCH	1119 AM	309 PM	230	8.0	8.0	8.0	1840		
011				ROOF - CENTRAL AREA	1125 AM	315 PM	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By: I. J. Funkley	19. Received By: D. Funkley	20. Date: 8/5/02	21. Time: 2:00 PM
26. ATC Project Manager: Andreas Andreou	27. Result To: A. Andreou	Beeper/Phone #'s: 646-772-1153	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ELAP	23. Date: 8/5/02	24. Time: 10:20
a. Analyzed By: CHAD		
b. QC By:		
c. Lab Batch #: 6939		
25. Microscope Make/Serial #:		
☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079		
28. Comments:		
Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA		

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011275839



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page 11 of 11

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: NYC BOE	2. Project Name: PS 89M	3. Project #: 14584	4. Project Monitor: DANIEL ROY Finkley	4c. Rotameter Number: HP 185
5. Date: TUES 3/5/02	2a. Project Address: 201 WARREN ST	3a. Task #:	4a. Air Sampler:	
6. Abatement Location: ALL FLOORS, PLAYGROUND + ROOF.	7. ☐ PCM (0.3 micron MCE) Cassette/Filter Manufacture: Lot #:	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture: MULTIMETRICS Lot #:	9. Type: a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☒ Environmental g. ☐ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location AT BREATHING ZONE			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
019				Field Blank open.									
012		Side		CLASS ROOM, NORTH VENT. RM 430	2:59 PM	6:49 PM	230	8.0	8.0	8.0	1840		
013				CLASS ROOM, EAST VENT. RM 310	3:11	7:01	230	8.0	8.0	8.0	1840		
014				CLASS ROOM, SOUTH VENT. RM 200	2:53	6:43	230	8.0	8.0	8.0	1840		
015				2ND FLOOR - HALLWAY SOUTHEAST	2:50 PM	6:40 PM	230	8.0	8.0	8.0	1840		
016		V		4th floor - HALLWAY SOUTHEAST	2:55 PM	6:45 PM	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By: J. Finkley	19. Received By: R. Rogers	20. Date: 3/5/02	21. Time: 2:00
26. ATC Project Manager: Andreas Andreou	27. Result To: A. Andreou	Beeper/Phone #'s: 646-772-1153	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: TEM	23. Date: 3/5	24. Time: 10:20
a. Analyzed By: OFFER		
b. QC By:		
c. Lab Batch #: 6939		
25. Microscope Make/Serial #: ☐ Nikon Labophot 233913 ☐ Nikon Labophot 233917 ☐ Nikon Labophot 233079 Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA		
28. Comments:		

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY-1 (1-01)

CITY_21MC100_011275840