



DURING School

AIR MONITORING DATA CHAIN OF CUSTODY FORM

KUSH

Page 7 of 11

TURNAROUND TIME			
☐ 2 hrs	☐ 6 hrs	☐ 48 hrs	☐ Standard
☐ 4 hrs	☐ 24 hrs	☐ 72 hrs	☐ Other

PROJECT INFORMATION

1. Client: NYC BOE	2. Project Name: PS 89M	3. Project #: 0819	4. Project Monitor: Daniel Finkley	4c. Rotameter Number: HP125
5. Date: 3/21/02	2a. Project Address: 201 WARREN ST.	3a. Task #:	4a. Air Sampler:	
6. Abatement Location: ALL FLOORS PLAYGROUND/ROOF	7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: Lot #:	8. ☒ TEM (0.45 micron MCE) MULTI-METRICS Cassette/Filter Manufacture: Lot # 00266910	9. Type: a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
017				Field Blank CLOSED									
				Field Blank									
01		IN		Cateteria -	7:55	11:45 AM	230	8.0	8.0	8.0	1840		
02		↓		1st floor Hallway	7:57	11:47 AM	230	8.0	8.0	8.0	1840		
				OUTSIDE Cateteria									
03		OUT		Play Ground - NORTH END	8:05	11:55 AM	230	8.0	8.0	8.0	1840		
04		↓		Play Ground - SOUTH END	8:07	11:57 AM	230	8.0	8.0	8.0	1840		
05		IN		2ND FLOOR - AUDITORIUM	7:42	11:32 AM	230	8.0	8.0	8.0	1840		
				REAR N. E. QUAD. Between COLUMNS									
06		↓		3RD FLOOR - GYMNASIUM	7:47	11:37 AM	230	8.0	8.0	8.0	1840		
				REAR S. E. QUAD.									

CHAIN OF CUSTODY

18. Relinquished By: I II III	19. Received By: Y. Efsthayou	20. Date: 3/21/02	21. Time: 8 PM
26. ATC Project Manager: Yiannis Efsthayou	27. Result To: Y. Efsthayou Beeper/Phone #s: 646.772.1155		

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC ELAP	23. Date: 3/21	24. Time: 22:15	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: Y. Efsthayou			Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA
b. QC By:			
c. Lab Batch #:			
28. Comments:			

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field NY-1 (1/01)

CITY_21MC100_011276014



DURING
SCHOOL

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

14584-0819
RUSH

Page 311 of 311

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other

PROJECT INFORMATION

1. Client: NYC BOE	2. Project Name: PS 89M	3. Project #: 14584-0819	4. Project Monitor: Daniel Funkley	4c. Rotameter Number: HP125
5. Date: 3/21/02	6. Abatement Location: ALL FLOORS, PLAYGROUND/ROOF	7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: Lot #	8. ☒ TEM (0.45 micron MCE) MULTI-METRICS Cassette/Filter Manufacture: Lot #	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number		11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
			12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
018					Field Blank CLOSED.									
					Field Blank									
07				OUT SIDE	ROOF - CENTRAL	8:23	12:13 PM	230	8.0	8.0	8.0	1840		
08			IN SIDE		1st floor Hallway	11:47	3:37	230	8.0	8.0	8.0	1840		
					outside cafeteria									
09				OUT SIDE	PLAYGROUND - NORTH END	11:55	3:45	230	8.0	8.0	8.0	1840		
010					PLAYGROUND - SOUTH END	11:57	3:47	230	8.0	8.0	8.0	1840		
011					ROOF -	12:13 PM	4:03	230	8.0	8.0	8.0	1840		

CHAIN OF CUSTODY

18. Relinquished By: I II III	19. Received By: ALI	20. Date: 3/21/02	21. Time: 8 PM
---	--------------------------------	-----------------------------	--------------------------

26. ATC Project Manager: Yiannis Efsthay	27. Result To: Y. Efsthay Beeper/Phone #'s: 646.772.1155
--	---

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC	23. Date: 3/21	24. Time: 22:15	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: ATC			Analysis Methodology PCM - NIOSH 7400A TEM - AHERA
b. QC By:			
c. Lab Batch #:			
28. Comments:			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011276015



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH
14584-

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: NYC BOE	2. Project Name: PS 89M	3. Project #: 14584-0819	4. Project Monitor: Daniel Funkley	4c. Rotameter Number: HP125
5. Date: 1/10/02	2a. Project Address: 201 WARREN ST.	3a. Task #:	4a. Air Sampler:	
6. Abatement Location: ALL FLOORS PLAYGROUND/ROOF	☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture: Lot #:	8. ☒ TEM (0.45 micron MCE) MULTI-METRICS Cassette/Filter Manufacture: Lot #:	9. Type: a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number		11. Pump Number		12. Sample Location		13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank										
				Field Blank										
012				CLASS ROOM 528 NORTH		2:55	5:55	180	10°	10°	10°	1800		
				- VENT										
013				CLASS ROOM 402		3:00	6:00	180	10°	10°	10°	1800		
				SOUTH VENT.										
014				CLASS ROOM 504		3:05	6:05	180	10°	10°	10°	1800		
				EAST VENT										
015				2ND FLOOR Hallway		2:43	5:43	180	10°	10°	10°	1800		
				SOUTH END										
016				3rd 4th Floor Hallway		2:47	5:47	180	10°	10°	10°	1800		
				SOUTH END										

CHAIN OF CUSTODY

18. Relinquished By: I. Funkley	19. Received By: Y. Efsthay	20. Date: 3/21/02	21. Time: 8:00 PM
25. ATC Project Manager: Yiannis Efsthay		27. Result To: Y. Efsthay Beeper/Phone #'s: 646.772.1155	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC ELAP	23. Date: 3/21	24. Time: 22:15	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: W. Jones			
b. QC By:			
c. Lab Batch #:			Analysis Methodology PCM - NIOSH 7400A TEM - AIHRA
28. Comments:			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_011276016