



AIR MONITORING DATA AND

CHAIN OF CUSTODY FORM

Page I of II

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other RUSH

PROJECT INFORMATION

1. Client: NYC-BOE
 2. Project Name: PS 89M
 2a. Project Address: 201 WARREN STREET
 3. Project #: 14584
 3a. Task #: 71084
 4. Project Monitor: Daniel Funkley
 4a. Air Sampler: HP 69
 4c. Rotameter Number: HP 69
 5. Date: THUR 01/17/02
 6. Abatement Location: 1ST FLOOR HALL
 7. ☐ PCM (0.6 micron MCE)
 Cassette/Filter Manufacture: MULTIMETER
 Lot #: 411-00202411
 8. ☒ TEM (0.45 micron MCE)
 Cassette/Filter Manufacture: MULTIMETER
 Lot #: 411-00202411
 9. Type:
 a. ☐ Background d. ☐ Post-Abate
 b. ☐ Pre-Abate e. ☐ OSHA
 c. ☐ Abatement f. ☐ Environmental
 g. ☐ Ambient
 h. ☒ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
013				Field Blank									
014				Field Blank									
01				Playground NORTH ONSTAND 6' from Basketball Hoop	7:22	11:22	240	8.0	8.0	8.0	1920		
02				Playground SOUTH ONSTAND 10' from Play zone.	7:24	11:24	240	8.0	8.0	8.0	1920		
03				1ST FLOOR HALLWAY ONSTAND MIDDLE of corridor	7:26	11:27	241	8.0	8.0	8.0	1928		
04				ROOF NORTH = ONSTAND Middle	7:39	11:40	241	8.0	8.0	8.0	1928		
05				5TH FLOOR SOUTH SIDE BETWEEN CLASS RM DOORS	7:32	11:32	240	8.0	8.0	8.0	1920		
06				2ND FLOOR SOUTH SIDE BETWEEN CLASS RM DOORS	7:44	11:44	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

18. Relinquished By: D. Funkley
 19. Received By: R. Ray
 20. Date: 1/18/02
 21. Time: 5:00
 26. ATC Project Manager: A. Andreou
 27. Result To: ANDREAS Andreou
 Beeper/Phone #'s: 646 772 1153

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: _____
 a. Analyzed By: _____
 b. QC By: _____
 c. Lab Batch #: _____
 23. Date: _____
 24. Time: _____
 25. Microscope Make/Serial #: _____
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079
 Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003271217



6363

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

RUSH

Page 11 of 11

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard ☒ Other RUSH
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs

PROJECT INFORMATION

1. Client: NYC BOE	2. Project Name: P589M	3. Project #: 14584-0819	4. Project Monitor: Daniel Funkley	4c. Rotameter Number: HP 69
5. Date: THUR 11/17/02	6. Abatement Location: PLAYGROUND, ROOF, 5TH & 2ND FLOOR 1ST FLOOR HALLWAY	7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture: Lot #:	8. ☐ TEM (0.45 micron MCE) MULTIMETRIC Cassette/Filter Manufacture: Lot # 00263916	9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location AT BREATHING ZONE			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
015				Field Blank OPEN									
				Field Blank									
07				PLAYGROUND NORTH SIDE	01122	1525	243	8.0	8.0	8.0	1944		
08				ON STAND - NEAR BASKETBALL HOOP	01134	1527	243	8.0	8.0	8.0	1944		
09				PLAYGROUND SOUTH SIDE	01127	1529	242	8.0	8.0	8.0	1936		
				ON STAND - middle of corridor									
010				1ST FLOOR HALLWAY	01141	1545	244	8.0	8.0	8.0	1952		
				ROOF (NORTH SIDE) STAND									
011				ON STAND middle of ROOF	01132	1548	256	8.0	8.0	8.0	2048		
				5TH FLOOR SOUTHSIDE SIDE									
012				ON STAND - 5TH FLOOR SOUTHSIDE SIDE	01145	1550	245	8.0	8.0	8.0	1960		
				ON STAND - 2ND FLOOR SOUTHSIDE SIDE									

CHAIN OF CUSTODY

18. Relinquished By: I Daniel Funkley	19. Received By: RR	20. Date: 11/18/02	21. Time: 5:00
26. ATC Project Manager: A Andreou	27. Result To: ANDREAS ANDREOU	Beeper/Phone #s: 646 772 1153	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:		
b. QC By:		
c. Lab Batch #:		
25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079		
28. Comments:		
Analysis Methodology PCM - NIOSH 7400A TEM - AHERA		

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)

CITY_21MC100_003271218