



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name <u>P.S. 234 M</u>		3. Project #		4. Project Monitor: <u>H. Antonyan</u>		4c. Rotameter Number: <u>HP-128</u>	
5. Date: <u>8/20/02</u>		6. Abatement Location: <u>Entire</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
<u>16</u>				<u>Field Blank</u>									
<u>17</u>				<u>Field Blank</u>									
<u>01</u>		<u>1</u>		<u>First floor - hallway</u>	<u>07:10</u>	<u>11:10</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		
<u>02</u>		<u>1</u>		<u>Cafeteria</u>	<u>07:13</u>	<u>11:14</u>	<u>241</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1928</u>		
<u>03</u>		<u>1</u>		<u>Gymnasium</u>	<u>07:16</u>	<u>11:18</u>	<u>242</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1936</u>		
<u>04</u>		<u>1</u>		<u>Auditorium</u>	<u>07:20</u>	<u>11:22</u>	<u>242</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1936</u>		
<u>05</u>		<u>1</u>		<u>North playground</u>	<u>07:25</u>	<u>11:28</u>	<u>243</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1944</u>		
<u>06</u>		<u>1</u>		<u>West playground</u>	<u>07:29</u>	<u>11:33</u>	<u>244</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1952</u>		

CHAIN OF CUSTODY

18. Relinquished By: <u>I H. Antonyan</u>	19. Received By: <u>M. Wall ATC</u>	20. Date: <u>8/20/02</u>	21. Time: <u>8:00 PM</u>
26. ATC Project Manager: _____			
27. Result To: _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC TEM</u>	23. Date: <u>8/21/02</u>	24. Time: <u>11:30</u>	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>R. Uy</u>			
b. QC By:			
c. Lab Batch #: <u>8726</u>			
28. Comments:			Analysis Methodology <u>PCM - NIOSH 7400A</u>

CITY_21NC100_011276679



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 2 of 3**TURNAROUND TIME**

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name: <u>PS 234 M.</u>		3. Project #:		4. Project Monitor: <u>H. Antonyan</u>		4c. Rotameter Number: <u>HP-128</u>	
		2a. Project Address: <u>292 Greenwich St. NY, NY</u>		3a. Task #:		4a. Air Sampler:			
5. Date: <u>8/20/02</u>		6. Abatement Location: <u>Entire</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture: _____ Lot #: _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture: <u>MMI</u> Lot #: <u>02106916</u>		9. Type: a. ☐ Background c. ☐ Abatement b. ☐ Pre-Abate d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
<u>18</u>				Field Blank <u>Sealed Blank</u>									
				Field Blank									
<u>07</u>			<u>1</u>	<u>Roof South part</u>	<u>07:34</u>	<u>11:37</u>	<u>243</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1944</u>		
<u>08</u>			<u>1</u>	<u>First floor Hallway</u>	<u>11:10</u>	<u>15:12</u>	<u>242</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1936</u>		
<u>09</u>			<u>1</u>	<u>North Play Ground</u>	<u>11:28</u>	<u>15:30</u>	<u>242</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1936</u>		
<u>10</u>			<u>1</u>	<u>West Play Ground</u>	<u>11:33</u>	<u>15:34</u>	<u>241</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1928</u>		
<u>11</u>			<u>1</u>	<u>Roof South Part</u>	<u>11:37</u>	<u>15:41</u>	<u>244</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1952</u>		
<u>12</u>			<u>1</u>	<u>Classroom # 216</u>	<u>13:40</u>	<u>17:40</u>	<u>240</u>	<u>8.0</u>	<u>8.0</u>	<u>8.0</u>	<u>1920</u>		

CHAIN OF CUSTODY

18. Relinquished By: <u>I H L S</u>		19. Received By: <u>M. Miller</u>		20. Date: <u>8/20/02</u>	21. Time: <u>8:00 AM</u>
II					
III					

26. ATC Project Manager:

27. Result To:

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>		23. Date: <u>8/20/02</u>	24. Time: <u>11:50</u>
a. Analyzed By: <u>R. J. G.</u>			
b. QC By:			
c. Lab Batch #: <u>3726</u>			

28. Comments:

25. Microscope Make/Serial #:

- ☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology

PCM - NIOSH 7400A

CITY_21MC100_011276680



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 3 of 3**TURNAROUND TIME**

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other Rush

PROJECT INFORMATION

1. Client: <u>NYC - BOE</u>		2. Project Name <u>PS 234 M</u>		3. Project #		4. Project Monitor: <u>H. Antonyan</u>		4c. Rotameter Number: <u>HP-128</u>	
		2a. Project Address <u>292 Greenwich St NY NY</u>		3a. Task #		4a. Air Sampler: <u>H. Antonyan</u>			
5. Date: <u>8/20/02</u>		6. Abatement Location: <u>Entire</u>		7. ☐ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture <u>MMI</u> Lot # <u>02106916</u>		9. Type: a. ☐ Background c. ☐ Abatement b. ☐ Pre-Abate d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
13		1		Classroom # 220	13:45	17:45	240	8.0	8.0	8.0	1920		
14		1		Classroom # 229	13:54	17:55	241	8.0	8.0	8.0	1928		
15		1		Classroom # kindergarten	14:00	18:00	240	8.0	8.0	8.0	1920		

CHAIN OF CUSTODY

18. Relinquished By: <u>I. H. Antonyan</u>	19. Received By: <u>[Signature]</u>	20. Date: <u>8/20/02</u>	21. Time:
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: <u>ATC-TEM</u>	23. Date: <u>8/20/02</u>	24. Time: <u>11:50</u>	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: <u>[Signature]</u>			
b. QC By: <u>[Signature]</u>			
c. Lab Batch: <u>8726</u>			Analysis Methodology <u>PCM - NIOSH 7400A</u>
26. ATC Project Manager:			
27. Result To:			28. Comments: <u>[Signature]</u>

CITY_21MC100_011276681