

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT


Page 1 of 6

LOCATION ps. BOM DATE 9/14/01 PROJECT NO. 19125-0242

Location	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
Outdoors					0.6	Raining.
Room 511					4	
Hallway 5th floor					3	
Room 510					4	
501					3	
Boys Bathroom					3	
506					2	
503					1	
501					1	
502					0.0	
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) ☒ Does () Does not meet established indoor air quality guidelines.

Signature:  Date: 9/14/01

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT


Page 2 of 6

LOCATION PS 130M DATE 9/14/01 PROJECT NO. 19125-0243

Location	Temperature (F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
401					0.0	
402					0.0	
406					1	
405					2	
Boys Toilets					3	
407					3	
408					2	
409					3	
412					4	
411					2	
Guideline levels ASHRAE/AIHA	69 - 76°F/winter 73-78.5°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	50 ug/m ³	1 ppm

Comments: _____

The assessed location(s) ☒ Does () Does not meet established indoor air quality guidelines.

Signature:  Date: 9/14/01