

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280

Fax: (212) 353-8306



Attn: Benjamin Sallemi

ATC Associates Inc.

104 East 25th Street

New York

NY 10010

Fax: (212) 353-3599

Phone: (212) 353-8280

Received: 10/2/02

8:00:00 AM

ATC Group #: 8923

Analysis Date: 10/2/02

Project: DEP Clean-up ATC Project #: 22906-0002

125 Cedar Street, New York, NY

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed
by EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures		Analytical Sensitivity (S/cc)	Asbestos Concentration		Notes
					0.5µ-5	5µ		(S/mm²)	(S/cc)	
1 8923 -1	1800.00	0.0450	0	None Detected	0	0	0.0048	<22.24	<0.0048	
2 8923 -2	180.00	0.4384	0	None Detected	0	0	0.0049	<2.28	<0.0049	
3 8923 -3	180.00	0.4384	0	None Detected	0	0	0.0049	<2.28	<0.0049	
4 8923 -4	1804.00	0.0450	0	None Detected	0	0	0.0047	<22.24	<0.0047	
5 8923 -5	1804.00	0.0450	0	None Detected	0	0	0.0047	<22.24	<0.0047	

MARK PEYSAKHOV

Analyzed by:

A handwritten signature in black ink, appearing to read 'Mark Peysakhov'.

MICHAEL A. GORYCKI, Ph.D.

Approved by:

A handwritten signature in black ink, appearing to read 'Michael A. Gorycki'.

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

Page 1 of 1

CITY_21MC100_003069216



AIR MONITORING AND CHAIN OF CUSTODY FORM

 Page _____
 TURNAROUND TIME:

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

Client: DEP	2. Project Name: 8923 518 DEP Clean up	3. Project #: 3349-3356	4. Project Monitor: _____
	2a. Project Address: 125 CECESTON RD	3a. Task #: 02	4a. Air Sampler: SD 005
5. Date: 02/10	6. Abatement Location: PM 10	7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: X Lot #: _____	8. ☒ TEM (0.45 micron MCE) Cassette/Filter Manufacture: MOT Lot #: 916
		9. Type: a. ☐ Background b. ☐ Pre-Abate	c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☒ Other: 100%

DAILY AIR SAMPLE RECORD

0. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
3132				Field Blank									
133				Field Blank Sealed Blank									
1			V	outside bldg north side up the scaffolding	1430	2200	450	4	4	4	1800		
2			V	" " " "	1435	2205	450	4	4	4	1800		
3			V	" " " "	1437	2207	450	4	4	4	1800		
4			V	" " " "	1439	2210	451	4	4	4	1804		
5			V	" " " "	1441	2212	451	4	4	4	1804		

CHAIN OF CUSTODY

8. Relinquished By: [Signature]	19. Received By: JR	20. Date: 02/02/02	21. Time: 8am
26. ATC Project Manager: B. Syllami			
27. Result To: 15. Syllami		Beeper/Phone #'s: _____	

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: TEC	23. Date: 02/02	24. Time: 10:05	25. Microscope Make/Serial #: ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: [Signature]			
b. QC By: _____			
c. Lab Batch #: _____			Analysis Methodology: PCM - NIOSH 7400A TEM - AHERA
28. Comments: _____			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)