



AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page 1 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☒ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP		2. Project Name: DEP Clean-up		3. Project #: 15-22306-0002		4. Project Monitor:		4c. Rotameter Number: SD-006	
		2a. Project Address: 125 Cedar St. NY		3a. Task #: 00002		4a. Air Sampler: E. Lewanovich			
5. Date: 10.07.02		6. Abatement Location:		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture: _____ Lot #: 01283108		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture: _____ Lot #: _____		9. Type: a. ☐ Background b. ☐ Pre-Abate	
						c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA		f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number		11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
			12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
					Field Blank									
					Field Blank									
FB-PH-01			✓		13 Floor Pent house	16:31	22:55	384	10	10	10	3840	4/100	<0.001
FB-PH-02			✓		---	16:33	22:56	383	10	10	10	3830	3/100	<0.001
FB-PH-03			✓		---	16:35	22:57	382	10	10	10	3820	3/100	<0.001
FB-PH-04			✓		---	16:37	22:58	381	10	10	10	3810	2/100	<0.001
FB-PH-05			✓		---	16:39	22:59	380	10	10	10	3800	3/100	<0.001
FB-12N-06			✓		12 Floor Apartment North	16:44	23:05	381	10	10	10	3810	4/100	<0.001
FB-12N-07			✓		---	16:46	23:06	380	10	10	10	3800	3/100	<0.001
FB-12N-08			✓		---	16:48	23:07	379	10	10	10	3790	5/100	<0.001
FB-12N-09			✓		---	16:50	23:08	378	10	10	10	3780	4/100	<0.001
FB-12N-10			✓		---	16:52	23:09	377	10	10	10	3770	1/100	<0.001
FB-12SW-11			✓		12 Floor Apartment SW	16:57	23:12	375	10	10	10	3750	58/100	<0.001
FB-12SW-12			✓		---	16:59	23:13	374	10	10	10	3740	108/100	<0.001

CHAIN OF CUSTODY

18. Relinquished By: I E. Lewanovich		19. Received By: A. Elbert		20. Date: 10.8.2	21. Time: 11:20
II					
III					
26. ATC Project Manager: B. Sallemi		27. Result To: B. Sallemi Beeper/Phone #'s: _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC		23. Date: 10/07/02	24. Time: 1850
a. Analyzed By: Phog			
b. QC By: _____			
c. Lab Batch #: 101526			
25. Microscope Make/Serial #: OLYMPUS C4510 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079			
28. Comments:			
Analysis Methodology ☒ PCM - NIOSH 7400 B. S. TEM - AHERA			

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING ATA AND CHAIN OF CUSTODY FORM

 Page 2 of 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☒ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP		2. Project Name: DEP Clean-up		3. Project #: 15-22306-0002		4. Project Monitor:		4c. Rotameter Number: SD-006	
		2a. Project Address: 125 Cedar St NY		3a. Task #: 50002		4a. Air Sampler: E. Lemanovich			
5. Date: 10.0.02		6. Abatement Location:		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot #: 91283108		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type: a. ☐ Background d. ☐ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA	
								f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
FB-12SW-13		✓		12 Floor, Apartment SW	17:01	23:14	373	10	10	10	3730	4/100	<0.001
FB-12SE-14		✓		12 Floor, Apartment SE	17:05	23:17	372	10	10	10	3720	5/100	<0.001
FB-12SE-15		✓		— — —	17:07	23:18	371	10	10	10	3710	4/100	<0.001
FB-12SE-16		✓		— — —	17:09	23:19	370	10	10	10	3700	8/100	<0.001
FB-12SE-17		✓		— — —	17:11	23:20	369	10	10	10	3690	8/100	<0.001
FB-12SE-18		✓		— — —	17:13	23:21	368	10	10	10	3680	5/100	<0.001
FB-11W-19		✓		11 Floor, Apartment North	17:19	23:24	365	10	10	10	3650	7/100	<0.001
FB-11W-20		✓		— — —	17:21	23:25	364	10	10	10	3640	6/100	<0.001
FB-11W-21		✓		— — —	17:23	23:26	363	10	10	10	3630	7/100	<0.001
FB-11W-22		✓		— — —	17:25	23:27	362	10	10	10	3620	5/100	<0.001
FB-11W-23		✓		— — —	17:27	23:28	361	10	10	10	3610	4/100	<0.001
FB-11S-24		✓		11 Floor, Apartment South	17:33	23:35	362	10	10	10	3620	4/100	<0.001

CHAIN OF CUSTODY

18. Relinquished By: E. Lemanovich		19. Received By: A. Elbert		20. Date: 10.8.2	21. Time: 11:00
II					
III					
26. ATC Project Manager: B. Sallawi		27. Result To: B. Sallawi			
		Beeper/Phone #'s _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC		23. Date: 10/02/02		24. Time: 18:50	
a. Analyzed By: AKG					
b. QC By: _____					
c. Lab Batch #: 101526					
28. Comments:					
25. Microscope Make/Serial #: OLYMPUS 0191/002 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079 Analysis Methodology ☒ PCM - NIOSH 7400 AB ok TEM - AHERA					

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING ATA AND CHAIN OF CUSTODY FORM

Page 3

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☒ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP		2. Project Name: DEP Clean - up		3. Project #: 15-22906-0002		4. Project Monitor:		4c. Rotameter Number: S.D-006	
		2a. Project Address: 125 Cedar St NY		3a. Task #: 00002		4a. Air Sampler: E. Lemmonovich			
5. Date: 10.0.02		6. Abatement Location:		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot #: 01283108		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type: a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location			13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA	12c. Sample Coordinates	13a. Start	13b. End	13c. Total	14a. Start	14b. End	14c. Avg			
				Field Blank									
				Field Blank									
FB-11S-25		✓		11 Floor Apartment South	17:35	23:36	361	10	10	10	3610	16/100	0.002
FB-11S-26		✓		---	17:37	23:37	360	10	10	10	3600	5/100	<0.001
FB-11S-27		✓		---	17:39	23:39	360	10	10	10	3600	9/100	<0.001
FB-11S-28		✓		---	17:41	23:41	360	10	10	10	3600	8/100	<0.001
FB-10N-29		✓		10 Floor Apartment North	17:57	23:57	366	10	10	10	3660	10/100	0.001
FB-10N-30		✓		---	17:53	23:53	365	10	10	10	3650	5/100	<0.001
FB-10N-31		✓		---	17:55	23:55	364	10	10	10	3640	4/100	<0.001
FB-10N-32		✓		---	17:57	24:00	363	10	10	10	3630	3/100	<0.001
FB-10N-33		✓		---	17:59	00:01	362	10	10	10	3620	5/100	<0.001
FB-10S-34		✓		10 Floor Apartment South	18:27	00:36	368	10	10	10	3680	5/100	<0.001
FB-10S-35		✓		---	18:29	00:36	367	10	10	10	3670	7/100	<0.001
FB-10S-36		✓		---	18:31	00:37	366	10	10	10	3660	3/100	<0.001

CHAIN OF CUSTODY

18. Relinquished By: E. Lemmonovich		19. Received By: A. Elbert		20. Date: 10.8.2	21. Time: 11:10 am
II					
III					
26. ATC Project Manager: B. Sallemi		27. Result To: B. Sallemi Beeper/Phone #'s _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC		23. Date: 10/02/02	24. Time: 18:50	25. Microscope Make/Serial #: OLYM BUS 1021025 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079
a. Analyzed By: R. Lopez				
b. QC By: _____				
c. Lab Batch #: 101526				Analysis Methodology ☒ PCM - NIOSH 7400 B. Sallemi ☐ TEM - AHERA
28. Comments:				

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)



AIR MONITORING ATA AND CHAIN OF CUSTODY FORM

Page 4

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☒ 24 hrs ☐ 72 hrs ☐ Other _____

PROJECT INFORMATION

1. Client: DEP		2. Project Name: DEP Clean-up		3. Project #: 15-22906-0002		4. Project Monitor:		4c. Rotameter Number:	
		2a. Project Address: 125 Cedar St. NY		3a. Task #: 00002		4a. Air Sampler: E. Lemanovich			
5. Date: 10.07.02		6. Abatement Location:		7. ☒ PCM (0.8 micron MCE) Cassette/Filter Manufacture _____ Lot #: 01283108		8. ☐ TEM (0.45 micron MCE) Cassette/Filter Manufacture _____ Lot # _____		9. Type: a. ☐ Background d. ☐ Post-Abate b. ☐ Pre-Abate e. ☐ OSHA	
								f. ☐ Environmental g. ☐ Ambient h. ☐ Other	

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location		12c. Sample Coordinates	13. Time (24 hrs clock)			14. Flow Rate (L/min.)			15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
		12a. IWA	12b. OWA		13a. Start	13b. End	13c. Total	14a. Start	14b. End	14b. Avg			
				Field Blank									
				Field Blank									
FB-108-37		✓		10 Floor, Apartment South	18:33	00:39	365	10	10	10	3650	14/100	0.002
FB-108-38		✓		---	18:35	00:39	364	10	10	10	3640	6/100	<0.001
39, 40				Blanks							-	0/100, 0/100	-
41, 42				Blanks							-	0/100, 0/100	-

CHAIN OF CUSTODY

18. Relinquished By: E. Lemanovich		19. Received By: A. Elbert		20. Date: 10.8.2	21. Time: 11:10
II					
III					
26. ATC Project Manager: B Sallemi		27. Result To: B Sallemi Beeper/Phone #'s _____			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name: ATC		23. Date: 10/08/02		24. Time: 1850	
a. Analyzed By: [Signature]					
b. QC By: _____					
c. Lab Batch #: 101526					
25. Microscope Make/Serial #: OLYMPUS C121015 ☐ Nikon Labophot 238913 ☐ Nikon Labophot 238917 ☐ Nikon Labophot 239079					
28. Comments:					
Analysis Methodology ☒ PCM - NIOSH 7400AB d.u. TEM - AHERA					

WHITE - File

YELLOW - Client/Report

PINK - Lab

GOLDENROD - Field

NY-1 (1/01)