



THE CITY OF NEW YORK DEPARTMENT OF ENVIRONMENTAL PROTECTION
JOEL A. MIELE, SR., P.E. Commissioner

ASBESTOS ANALYTICAL REPORT

PHONE (718) 595-4418
FAX (718) 595-4422

ASBESTOS CONTROL PROGRAM LABORATORY
96-05 HORACE HARDING EXPRESSWAY
CORONA, NEW YORK 11368
(718) 595-6309 FAX# (718) 595-6307

ROBERT C. AVALTRONI
Deputy Commissioner

Bureau of
Air, Noise, & Hazardous
Materials

ELAP # 11045

TEST METHODS: 1) 40 CFR Part 763, Subpart F, App. A
2) Polarized Light Microscopy plus Stratified Point-Counting Method
3) EPA/600/R-93/116

Incident #: 1H09111205
Inspector: W. MAN WONG
Premise: WORLD TRADE CENTER
Boro: Manhattan
Analyst: G. ANAKHU

Date Collected: 09/11/01
Received: 09/11/01
Analyzed: 09/11/01

Client #: 2
DEP Sample #: 10911/A216002
Laboratory #: 10911/605
Location Sampled:
Color: GREY
Homogenous: Yes
Asbestos Present: No

Results (%)

Cellulose 5
Fibrous glass 83
Silicates 2
Matrix 10

Comments: Three samples collected from Chris Haas vehicle were found to contain chrysotile. Two samples contained trace <1% chrysotile.

Reviewed by: *[Signature]*
Laboratory Director

This test report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by NVLAP or any other U.S. Government agency.

59-17 Junction Boulevard, 11th Floor, Corona, New York 11368-5107

