

ENVIRO-PROBE, INC.
2917 BRUCKNER BOULEVARD
BRONX, N.Y. 10461
(718)863-0045

CLIENT: Riverpoint, Inc.
 7 Hillside Ave, Suit 100
 New Rochelle, NY. 10801-1608

Job #:101171
File #: 23401
NYSELAP #:10898
AIHA-PAT #:102505

PROJECT LOCATION: WTC, Various Locations

CONTAMINANT INVESTIGATED: Asbestos Airborne

DATE MONITORED: 12/28/01

Samples Collected by: Client

METHOD OF ABATEMENT:

☐ CONTAINMENT

☐ GLOVE BAG

☐ TENT

☐ OTHER

NATURE OF TEST:

☐ PRE-TEST

☐ DURING PREPARATION

☐ DURING ASBESTOS REMOVAL

☐ DURING CLEAN-UP

☐ AFTER FINAL CLEAN-UP

☐ AIR-TEST

☐ OSHA

☐ AGGRESSIVE

☐ NON-AGGRESSIVE

OTHERS:

METHOD: NIOSH 7400, ISSUE 2-8/15/94

SAMPLING LOCATION	SAMPLE #	VOLUME OF AIR SAMPLED (LITERS)	RESULTS FIBERS/FIELD	RESULTS FIBERS/CC
Park Place/Church	01-12/25/01	666	<0.07	0.004
Park Place/Greenwich	02-12/25/01	666	<0.07	0.002
Murray/Church	03-12/25/01	666	<0.07	0.005
Murray/Greenwich	04-12/25/01	675	<0.07	0.003
Fulton/Church	05-12/25/01	675	<0.07	0.004
North End/Warren	06-12/25/01	843.5	0.08	0.006
West Street/Warren	07-12/25/01	657	0.105	0.008
Gateway Plaza	08-12/25/01	861.5	<0.07	0.005
South End/Albany	09-12/25/01	850.3	<0.07	0.004
West Street/Albany	10-12/25/01	850.3	0.085	0.007
Rector pl. by park	11-12/25/01	661.5	<0.07	0.004
3rd pl./South End	12-12/25/01	661.5	<0.07	0.003

METHOD: NIOSH 7400, Rule A (PCM)

*BDL - Below Detectable Levels

*These results apply to these particular samples

L.O.D. = 0.07 fibers/Field = 9 Fibers/mm2

[Signature]
 Analyst
[Signature]
 Lab Supervisor's Signature

These samples were not collected by Enviro-Probe

12/25/2001 20:14 9146321558

RIVERPOINT

PAGE 02

ENVIRO-PROBE, INC.
2917 BRUCKNER BOULEVARD
BRONX, N.Y. 10461
(718)863-0046

CLIENT: Riverpoint, Inc.
 7 Hillside Ave, Suit 100
 New Rochelle, NY. 10801-1608

Job #: 101171
File #: 23401
NYSELAP #: 10894
AHA-PAT #: 102609

PROJECT LOCATION: WTC, Various Locations

CONTAMINANT INVESTIGATED: Asbestos Airborne

DATE MONITORED: 12/25/01

Samples Collected by: Client

METHOD OF ABATEMENT:

☐ CONTAINMENT

☐ GLOVE BAG

☐ TENT

☐ OTHER

NATURE OF TEST:

☐ PRE-TEST

☐ DURING PREPARATION

☐ DURING ASBESTOS REMOVAL

☐ DURING CLEAN-UP

☐ AFTER FINAL CLEAN-UP

☐ AIR-TEST

☐ OSHA

☐ AGGRESSIVE

☐ NON-AGGRESSIVE

OTHERS:

METHOD: NIOSH 7400, ISSUE 2-4/15/94

SAMPLING LOCATION	SAMPLE #	VOLUME OF AIR SAMPLED (LITERS)	RESULTS FIBERS/FIELD	RESULTS FIBERS/CC
West End of W Thames	13-12/25/01	661.5	0.075	0.005
River Ter./ Park pl.	14-12/25/01	657	<0.07	0.002
River Ter./ Chambers	15-12/25/01	657	<0.07	0.004
River Ter./ Park pl.	16-12/25/01	657	0.085	0.008
North End/ Park pl.	17-12/25/01	843.5	<0.07	0.005
River Ter./ Vesey	18-12/25/01	843.5	<0.07	0.003
Trinity pl./ Thames	19-12/25/01	650.3	<0.07	0.004
Vesey/ West Broadway	20-12/25/01	666	<0.07	0.002
Field Blank	21-12/25/01		BDL	
Field Blank	22-12/25/01		BDL	

METHOD: NIOSH 7400, Rule A (PCM)

*BDL - Below Detectable Levels

*These results apply to these particular samples

-O.D. = 0.07 fibers/Field = 9 Fibers/mm²

[Signature]
 Analyst
[Signature]
 Lab Supervisor's Signature

These samples were not collected by Enviro-Probe

12/25/2001 20:14

9146321558

RIVERPOINT

PAGE 03