

Lower Manhattan Testing

Collection Date: 9/11/01

WTC PLM Sample Analysis Table

Location Sampled	Sample Typ	Other 3
211 Vehicle on Fender	Bulk	① 23 Barclay St nyc net Broadway + Church St
218 Vehicle on Front Hood	Bulk	
23 Barclay St	Bulk	
217 Broadway	Bulk	
Church St. & Vesey St		② bt
Church St. & Vesey St		
Across 90 Church St		
Barclay St & Church St		
Warren St & Church St		
Church St & Murray St		
Park Pl & Church St		
Church St. & Dey St		
Church St & Cortlandt St		

③ 90 Church St
bt Vesey St + Barclay St.

Lower Manhattan Testing

Collection Date: 9/11/01

WTC PLM Sample Analysis Table

Location Sampled	Sample Type	Asbestos Fiber Types	Fiber 2	Fiber 3
211 Vehicle on Fender	Bulk	CHRY <1%	Cell 12%	Fiberglass 44%
218 Vehicle on Front Hood	Bulk	—	Cell 5%	Fiberglass 83%
23 Barclay St	Bulk	CHRY 1%	—	—
217 Broadway	Bulk	CHRY 10%		
Church St. & Vesey St		217 Broadway bet Vesey St & Barclay St		
Church St. & Vesey St				
Across 90 Church St				
Barclay St & Church St				
Warren St & Church St				
Church St & Murray St				
Park Pl & Church St				
Church St. & Dey St				
Church St & Cortlandt St				

90 Church St
bet Vesey St & Barclay St.

Lower Manhattan Testing


Collection Date: 9/11/01

WTC PLM Sample Analysis Table

Location Sampled	Sample Type	Asbestos Fiber Types	Fiber 2	Fiber 3
211 Vehicle on Fender	Bulk	CHRY <1%	Cell 12%	Fiberglass 44%
218 Vehicle on Front Hood	Bulk	—	Cell 5%	Fiberglass 83%
23 Barclay St	Bulk	CHRY 1%	—	—
217 Broadway	Bulk	CHRY 4%	Cell 76%	Fiberglass 17%
Church St. & Vesey St	Bulk	—	Cell 45%	Fiberglass 30%
Church St. & Vesey St	Bulk	CHRY 1.3%	—	—
Across 90 Church St	Bulk	—	Cell 2%	Fiberglass 98%
Barclay St & Church St	Bulk	CHRY 4.8%	—	—
Warren St & Church St	Bulk	CHRY Trace	—	—
Church St & Murray St	Bulk	CHRY <1%	—	—
Park Pl & Church St	Bulk	CHRY 4% Almost Trace	—	—
Church St. & Dey St	Bulk	CHRY <1%	—	—
Church St & Cortlandt St	Bulk	CHRY <1%: Almost <1%	Cell 4%	Fiberglass 50%

Lower Manhattan Testing

Collection Date: 9/11/01



Lower Manhattan Testing

Collection Date: 9/11/01

WTC PLM Sample Analysis Table

Location Sampled	Sample Type	Asbestos Fiber Types	Fiber 2	Fiber 3
211 Vehicle on Fender *	Bulk	CHRY <1%	Cell 12%	Fiberglass 44% <i>deleted</i>
218 Vehicle on Front Hood *	Bulk	—	Cell 5%	Fiberglass 8% <i>?</i>
23 Barclay St	Bulk	CHRY 1%	—	—
217 Broadway	Bulk	CHRY 4%	Cell 76%	Fiberglass 17%
Church St. & Vesey St	Bulk	—	Cell 45%	Fiberglass 30%
Church St. & Vesey St	Bulk	CHRY 1.3%	—	—
Across 90 Church St	Bulk	—	Cell 2%	Fiberglass 98%
Barclay St & Church St	Bulk	CHRY 4.8%	—	—
Warren St & Church St	Bulk	CHRY Trace	—	—
Church St & Murray St	Bulk	CHRY <1%	—	—
Park Pl & Church St	Bulk	CHRY 4% Almost Trace	—	—
Church St. & Dey St	Bulk	CHRY <1%	—	—
Church St & Cortlandt St	Bulk	CHRY <1%:Almost <1%	Cell 4%	Fiberglass 50%

* No Location
MARKED ON
MAP.
M.

Lower Manhattan Testing

Collection Date: 9/11/01

