NYC 9/11 Public Portal Document

AIR MONITORING DATA AND CHAIN OF CUSTODY FORM

Page _____ of _____

TURNAROUND TIME

☐ 2 hrs ☐ 6 hrs ☐ 48 hrs ☐ Standard
☐ 4 hrs ☐ 24 hrs ☐ 72 hrs ☒ Other ASAP

PROJECT INFORMATION 6C29

1. Client:	2. Project Name / 2a. Project Address	3. Project #	4. Project Monitor / 4a. Air Sampler	4c. Rotameter Number
NYC - BOE	2a. Project Address 40 Trinity Place 12/27/2006	14584-0864	4. C. Mathew / 4a. C. Mathew	NYC HP3-S

5. Date:	6. ~~Abatement~~ Location:	7. ☐ PCM (0.8 micron MCE)	8. ☒ TEM (0.45 micron MCE)	9. Type:
12/29/01	Entire	Cassette/Filter Manufacture _____ Lot # _____	Cassette/Filter Manufacture _____ Lot # _____	a. ☐ Background b. ☐ Pre-Abate c. ☐ Abatement d. ☐ Post-Abate e. ☐ OSHA f. ☐ Environmental g. ☒ Ambient h. ☐ Other

DAILY AIR SAMPLE RECORD

10. Sample I.D. Number	11. Pump Number	12. Sample Location 12a. IWA	12b. OWA	12c. Sample Coordinates	13. Time (24 hrs clock) 13a. Start	13b. End	13c. Total	14. Flow Rate (L/min.) 14a. Start	14b. End	14b. Avg	15. Total Air Vol. (liters)	16. # Fibers/Fields Minus Blank	17. Fiber Conc. F/CC
				Field Blank									
				Field Blank									
1844-12/29-09		X		Inside CR # 1121	6:31	10:34	243	8.0	9.0	8.5	1944		
-10		X		Inside Library 13th Flr	6:33	10:36	243	8.0	8.0	8.0	1944		
-11			X	Roof over 14th Flr Machine Rm.	6:35	10:41	246	8.0	10.0	9.0	1968		

CHAIN OF CUSTODY

18. Relinquished By:	19. Received By:	20. Date:	21. Time:
I			
II			
III			

LAB INFORMATION (ATC ELAP # 10879, ATC NVLAP # 1187)

22. Lab Name:	23. Date:	24. Time:
a. Analyzed By:		
b. QC By:		
c. Lab Batch #:		

25. Microscope Make/Serial #:
☐ Nikon Labophot 238913
☐ Nikon Labophot 238917
☐ Nikon Labophot 239079

Analysis Methodology
PCM - NIOSH 7400A
TEM - AHERA

26. ATC Project Manager:

27. Result To: _____
Beeper/Phone #'s _____

28. Comments:

WHITE - File YELLOW - Client/Report PINK - Lab GOLDENROD - Field

NY 1 (1/00)

CITY_21MC100_0030590B6

NYC-WTC_000203594