

P.04



KAM CONSULTANTS
35-40 38th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC

SAMPLING DATE: 10-13-01

PROJECT: Stuyvesant H.S.

ADDRESS: 345 Chambers St, NY, NY 10282

T011013C

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (fibers/mm ³)	Structure Concentration (fibers/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
	PIER-25									
1	North Entrance of school-East	8:01	15:57	3	3	1428	0	0	<16.67	<0.0045
2	North Entrance of school-West	8:04	15:59	3	3	1425	0	0	<16.67	<0.0045

TECHNICIAN:

ROTAMETER: KAM101

CHAIN OF CUSTODY	Recs Analyze ASAP and Fax Results:	RECEIVED AT LAB BY:
	DDC Hazmat (718) 291-1499 DDC OPERATIONS (212) 941-5356 DDC Bob Adams (609) 584-1134	SAMPLE CONDITION UPON RECEIPT: 02:54 PM OCT 13 2001 DATE/TIME: 10/13/01

ANALYST:

DATE RECEIVED:

DATE OF ANALYSIS

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356

CITY_21MC100_003062282

DDC

OCT-14-2001 08:26