

DCAS

Fax: 212-669-2305

Oct 4 2001 17:35



KAM CONSULTANTS
35-40 36th Street
Long Island City,
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS**BUILDING ADDRESS:** OFFICE BLDG.- 2 Lafayette, Manhattan, NY**PROJECT#:**

Client Sample ID#:	1	2	3	4	5
Lab Sample ID#:	010917A-808	010917A-809	010917A-810	010917A-811	010917A-812
Sample Location:	5th Floor Stair "Y"	5th Floor Stair "W"	5th Floor Lobby By Elevators	12th Floor Elevators Lobby	12th Floor Stair "Y"
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Floor Wipe	Floor Wipe	Floor Wipe	Floor Wipe	Floor Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	0%	0%	0%	0%	0%
Other Fibr. Mat. (Type & Percent):	10%CELL	5%CELL	10%CELL 5%SYNTH	15%CELL	10%CELL
Non Fibr. Mat. (Percent):	90%	95%	85%	85%	90%
Date Received:	9/17/01				
Date of Analysis:	9/17/01				
Date of Report:	9/17/01				

Analyst:

George Kouvaras

Lab Manager:

David Chen

- Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- Samples will be stored for ninety (90) days and then returned to the client upon request
- The results relate only to the items calibrated or tested
- The certificate of report shall not be reproduced without the written approval of the laboratory.
- The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269

DCAS

Fax: 212-669-2805

000 4 01 11:02 11/01



KAIN CONSULTING
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: OFFICE BLDG.- 2 Lafayette, Manhattan, NY

PROJECT#:

Client Sample ID# :	6	7	8	9	10
Lab Sample ID# :	010917A-813	010917A-814	010917A-815	010917A-816	010917A-817
Sample Location:	12th Floor Stair "W"	9th Floor Elevator Lobby	7th Floor Lobby By Elevator	7th Floor Stairway "Y"	7th Floor Stairs "W"
Homogeneity:	Yes	Yes	Yes	Yes	Yes
Sample Description:	Floor Wipe	Floor Wipe	Floor Wipe	Floor Wipe	Floor Wipe
Color:	Blk	Blk	Blk	Blk	Blk
Texture:	Mixed	Mixed	Mixed	Mixed	Mixed
Sample Treatment:	None	None	None	None	None
Asbestos Present: (Type & Percent)	ND	ND	ND	ND	ND
Total Percent Asbestos:	0%	0%	0%	0%	0%
Other Fibr. Mat. (Type & Percent):	5%CELL	5%CELL 5%SYNTH	5%CELL	5%CELL	8%CELL 5%SYNTH
Non Fibr. Mat. (Percent):	95%	90%	95%	95%	87%
Date Received:	9/17/01				
Date of Analysis:	9/17/01				
Date of Report:	9/17/01				

Analyst:

George Kouvaras

Lab Manager:

David Chen

- Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- Samples will be stored for ninety (90) days and then returned to the client upon request
- The results relate only to the items calibrated or tested.
- The certificate of report shall not be reproduced without the written approval of the laboratory.
- The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 100269

DCAS

Fax: 212-669-2305

Oct 4 '01 17:52 7.00



KAM CONSULTANTS
35-40 36th Street
Long Island City,
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

BULK SAMPLE ANALYSIS REPORT

CLIENT: NYC-DCAS

BUILDING ADDRESS: OFFICE BLDG.- 2 Lafayette, Manhattan, NY

PROJECT#:

Client Sample ID#	11	12	13
Lab Sample ID#	010917A-818	010917A-819	010917A-820
Sample Location	3rd Floor Elevator Lobby	Ground Floor By Elevator #5	Ground Floor Stair "Y"
Homogeneity	Yes	Yes	Yes
Sample Description	Floor Wipe	Foot Step Wipe	Floor Wipe
Color	Blk	Blk	Blk
Texture	Mixed	Mixed	Mixed
Sample Treatment	None	None	None
Asbestos Present (Type & Percent)	ND	ND	ND
Total Percent Asbestos:	0%	0%	0%
Other Fibr. Mat. (Type & Percent):	10%CELL	10%CELL 5%SYNTH	10%CELL 5%SYNTH
Non Fibr. Mat. (Percent):	90%	85%	85%
Date Received:	9/17/01		
Date of Analysis:	9/17/01		
Date of Report:	9/17/01		

Analyst:

George Kouvaras

Lab Manager:

David Chen

- Analysis of samples is performed by Polarized Light Microscopy (PLM) - Point Counting Method (EPA 600/M4-82-020)
- Analytical equipments: Stereobinocular microscope (MEIJI EMT-Serial # 25930), Polarized Light Microscope (MEIJI ML-POL-Serial # 88034)
- PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. Quantitative transmission electron microscopy is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing
- Samples will be stored for ninety (90) days and then returned to the client upon request
- The results relate only to the items calibrated or tested.
- The certificate of report shall not be reproduced without the written approval of the laboratory.
- The report must not be used by the client to claim endorsement by NVLAP or any agency of the US Government.

NYS-DOH ELAP # 11273

NIST-NVLAP # 102047

AIHA #: 190269