

01/30/02 WED 13:39 FAX 518 485 1150
01/22/02 TUE 09:23 FAX 518 485 1150

NYSDOL-PESH
NYSDOL-PESH

014
002

**New York State Department of Labor
Public Employee Safety and Health Bureau**

Vehicle Contamination Sampling

SAMPLE # 11

Vehicle Location or ID: Fleet Maint. Ctr. 34th St. Long Island City

Vehicle Type: MP8707 Team 95

Asbestos

	Before vents turned on	After vents turned on
Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

Metals

Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>✓ Back seat</u> <i>Passenger</i>
	<u>Other:</u>	<u>Other:</u> <i>7 1/2 x 22</i>

Other: _____

Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

Sample Date: 1/22/02

Sampled By: Kevin Cox