

01/30/02 WED 13:39 FAX 518 485 1150

NYSDOL-PESH

012

01/22/02 TUE 09:23 FAX 518 485 1150

NYSDOL-PESH

002

**New York State Department of Labor
Public Employee Safety and Health Bureau**

Vehicle Contamination Sampling

SAMPLE # 9

Vehicle Location
or ID:

Fleet Maint. Ctr. - 34th St. Long Island City

Vehicle Type:

MP 8707 70Am 95

Asbestos

	Before vents turned on	After vents turned on
Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

Metals

Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>✓ Other: <u>Steering wheel</u></u>	<u>Other:</u>

Other: Steering Wheel

Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

Sample Date:

1/22/02

Sampled By:

Kevin Cox