

01/30/02 WED 13:39 FAX 518 485 1150

NYS DOL-PESH

011

01/22/02 TUE 09:23 FAX 518 485 1150

NYS DOL-PESH

002

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 8

Vehicle Location
or ID:

Fleet Maint Ctr. 34th St. Long Island City

Vehicle Type:

FP02002

Asbestos

	Before vents turned on	After vents turned on
Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

Metals

Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

Other: BLANK (comparison)

Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

Sample Date:

1/22/02

Sampled By:

Kevin Cox