NYC 9/11 Public Portal Document

NOT AT WTC

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 12

Vehicle Location or ID: Fleet Maint. Gar. 34th St. Long Island City

Vehicle Type: MP8707 Foam 95

Asbestos

	Before vents turned on	After vents turned on
Sample Location of wipe:	___Dashboard	___Dashboard
	___Front seat	___Front seat
	___Floor	___Floor
	___Back seat	___Back seat
	___Other:	___Other:

Metals

Sample Location of wipe:	___Dashboard	___Dashboard
	___Front seat	___Front seat
	___Floor	___Floor
	___Back seat	___Back seat
	___Other:	___Other:

Other: BLANK (comparison)

Sample Location of wipe:	___Dashboard	___Dashboard
	___Front seat	___Front seat
	___Floor	___Floor
	___Back seat	___Back seat
	___Other:	___Other:

Sample Date: 1/22/02

Sampled By: Kevin Cox

NYC-WTC_000205121