

01/30/02 WED 13:37 FAX 518 485 1150
01/22/02 TUE 09:23 FAX 518 485 1150

NYSDOL-PESH
NYSDOL-PESH

005
002

**New York State Department of Labor
Public Employee Safety and Health Bureau**

Vehicle Contamination Sampling

SAMPLE # 3

Vehicle Location
or ID:

Fleet Maint. Bldg. 34th St. Long Island City

Vehicle Type:

SL 01020 LADDER Co. #40

Asbestos

	Before vents turned on	After vents turned on
Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

Metals

Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	☒ <u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

*Right Passenger Se
8" x 12"*

Other: _____

Sample Location of wipe:	<u>Dashboard</u>	<u>Dashboard</u>
	<u>Front seat</u>	<u>Front seat</u>
	<u>Floor</u>	<u>Floor</u>
	<u>Back seat</u>	<u>Back seat</u>
	<u>Other:</u>	<u>Other:</u>

Sample Date: 1/22/02

Sampled By: Kevin Cox