

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 1-17-02-[#]8-15 (E. 3rd)

Vehicle Location
or ID:

Engine 33 - Ladder 9 - 42 Great Jones St.

Vehicle Type:

Ladder 9 Truck

Asbestos

Sample Location
of wipe:

Before vents turned on

☒ Dashboard - 8
☐ Front seat
☐ Floor
☐ Back seat
☐ Other:

After vents turned on

☒ Dashboard (near blower) - 10
☐ Front seat
☐ Floor
☐ Back seat
☒ Other: middle console (rear cab) - 13

Metals

Sample Location
of wipe:

☒ Dashboard
☒ Front seat (passenger) - 9
☐ Floor
☐ Back seat
☐ Other:

☐ Dashboard
☐ Front seat
☒ Floor (below blower) - 11 (passenger side)
☒ Back seat - 14
☐ Other:

Other: Mercury

Sample Location
of wipe:

☐ Dashboard
☐ Front seat
☐ Floor
☐ Back seat
☐ Other:

☐ Dashboard
☐ Front seat
☒ Floor (driver's side) - 12
☐ Back seat
☐ Other:

Was at site ~ 3 wks. after attack
(in-house decon)

Sample Date:

1-17-02

Sampled By:

M. Thorsland / C. Jay

Bldg. wipe -

corner of bldg.
from floor
below turnout
gear rack (#15)
(Asbestos)