

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 1-17-02-1-7

(E. 3rd)

Vehicle Location
or ID:Engine 33-Ladder 9 - 42 front Jones St.

Vehicle Type:

Engine 33 (Pumper)

Asbestos

Sample Location
of wipe:

Before vents turned on

After vents turned on

☒ Dashboard-1☒ Dashboard-3☐ Front seat☐ Front seat☐ Floor☐ Floor☐ Back seat☐ Back seat☐ Other:☒ Other: middle console rear
cabin-6

Metals

Sample Location
of wipe:☐ Dashboard☐ Dashboard☐ Front seat☐ Front seat☐ Floor☐ Floor☐ Back seat☒ Back seat-7☒ Other: Middle console-2☒ Other: Middle Console-4Other: MercurySample Location
of wipe:☐ Dashboard☐ Dashboard☐ Front seat☐ Front seat☐ Floor☐ Floor☐ Back seat☐ Back seat☐ Other:☒ Other: side of blower
unit near ceiling-5

At site initially (in-house decon)

Sample Date:

1-17-02

Sampled By:

M. Thorsland / C. Jay