NYC 9/11 Public Portal Document

New York State Department of Labor
Public Employee Safety and Health Bureau

Vehicle Contamination Sampling

SAMPLE # 1-17-02-#46-48

Vehicle Location or ID: Engine 22-Ladder 13 159 E. 85th St.

Vehicle Type: Ladder 13 (Seagrave) - #ST00002

Asbestos

Sample Location of wipe:	Before vents turned on	After vents turned on
	X Dashboard (top of radio) 46	___ Dashboard
	___ Front seat	___ Front seat
	___ Floor	___ Floor
	___ Back seat	___ Back seat
	___ Other:	___ Other:

Metals

Sample Location of wipe:		
	___ Dashboard	___ Dashboard
	___ Front seat	___ Front seat
	___ Floor	___ Floor
	___ Back seat	___ Back seat
	X Other: Middle console-47	___ Other:

Other: Mercury

Sample Location of wipe:		
	___ Dashboard	___ Dashboard
	___ Front seat	___ Front seat
	___ Floor	___ Floor
	___ Back seat	___ Back seat
	X Other: bottom of blower unit near windshield-48	___ Other:

(Truck at site initially) In-house decon

Vehicle left on call during sampling

Sample Date: 1/17/02

Sampled By: M. Thorsland / C. Jay

NYC-WTC_000205127