



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 3/21/02
ADDRESS: 345 Chambers St., NY, NY 10282
KAM CONSULTANTS

2002 MAR 21 PM 4:51

T020321C

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)
							0.5-5.0 (µ)	>5.0 (µ)		
1	North Exit of Stuyvesant H.S.	0700	0700	3	3	1800	0	0	1200	200043
2	North West Site	0701	0701	3	3	1800	0	0	1200	200043

TECHNICIAN: D. SALIS

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX RESULTS TO	RECEIVED AT LAB BY: G-4
	NYC D.D.C.	SAMPLE CONDITION UPON RECEIPT: Good
		DATE/TIME:

ANALYST: ALEXS BARNES DATE RECEIVED: 3-21

DATE OF ANALYSIS 3-22-02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356