



**35-40 35th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876**

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 3/17/02
ADDRESS: 345 Chambers St., NY, NY 10282

T020318A

[illegible]

KAMCONSULTANTS
202 MAR 18 AM 7:52

TECHNICIAN:

D. SALIS

ROTAMETER: KAM101

CHAIN OF CUSTODY	FOX RESULTS TO N+C D.D.C	RECEIVED AT LAB BY: <i>MS</i> SAMPLE CONDITION UPON RECEIPT: <i>Q23</i> DATE/TIME:
------------------------	-----------------------------	--

ANALYST:

ALAN BARENGOLB

DATE RECEIVED:

13-18

DATE OF ANALYSIS

3-7A

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)

Sample Volume may be below recommended limit of the method.

FAX RESULTS TO (212) 941-5356