

PAGE 01/01

KAM CONSULTANTS

71872933774

03/04/2002 13:55

CITY_21MC100_002988075



35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

FOR ASBESTOS AIR MONITORING

SAMPLING DATE: 3/3/02
ADDRESS: 345 Chambers St., NY, NY 10282

T020304 K

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc) 2002 MAR 4 KAM CONSULTANTS RECEIVED 30
							0.5-5.0 (μ)	>5.0 (μ)		
1	North Exit #25 Stuyvesant H.S.	07:00	17:00	3	3	1800	0	0	420.0	4000042
2	North west site	07:01	17:01	3	3	1800	0	0	420.0	4000042

TECHNICIAN: D. SALIS

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX RESULTS TO	RECEIVED AT LAB BY: <i>MS</i>
	N.Y.C. D.D.C.	SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST: *ALEX BOBROW* DATE RECEIVED: *3-4-02* DATE OF ANALYSIS: *3-04-02*

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)

Sample Volume may be below recommended limit of the method.

FAX RESULTS TO (212) 941-5356