



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 1/22/02
ADDRESS: 345 Chambers St. NYC 10008
RECEIVED
STUYVESANT H.S. MONITORING

2002 JAN 22 PM 6:56

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (m³)	STRUCTURES DETECTED		Structure Density (struct/m³)	Structure Concentration (struct/cc)
							0.5-5.0 (µ)	>5.0 (µ)		
1	North Exit of Stuyvesant H.S.	0700	1700	3	3	1800	0	0	<25.00	<0.0043
2	North west site	0701	1701	3	3	1800	0	0	<25.00	<0.0043

TECHNICIAN:

D. SALIS

ROTAMETER: KAM101

CHAIN OF CUSTODY	FOR results to	RECEIVED AT LAB BY: G. F. Good
	N.Y.C. D.D.C.	SAMPLE CONDITION UPON RECEIPT: Good
		DATE/TIME:

ANALYST:

[Signature]

DATE RECEIVED:

G. F. 1/22/02

DATE OF ANALYSIS

1/23/02

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.

FOR RESULTS TO (212) 641-5358

01/24/2002 14:59

7187293774

KAM CONSULTANTS

PAGE 01/03

CITY_21MC100_002988168

NYC-WTC_000205383