NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTOD. FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12/4/01
ADDRESS: 345 Chambers St., NY, NY 10282

T01205E

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
	PIER #25									
1	OUTSIDE NORTH ENTRANCE OF SCHOOL - EAST SIDE	16.01	23.57	3	3	1428	0	0	<18.51	<0.0052
2	↓ - WEST SIDE	16.02	23.58	3	3	1428	0	0	<18.51	<0.0052

TECHNICIAN: A. MARTIROSSIAN

ROTAMETER: KAM101

CHAIN OF CUSTODY	PLEASE, FAX RESULTS TO NYC DDC	RECEIVED AT LAB BY:
		SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST:

DATE RECEVED:

DATE OF ANALYSIS 12/7

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

RECEIVED
KAM CONSULTANTS
2001 DEC -5 AM 7:49

12/05/2001 13:05 7187293774 KAM CONSULTANTS PAGE 02/03

CITY_21MC100_002988228

NYC-WTC_000205389