



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1897
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12/11/01
ADDRESS: 345 Chambers St., NY, NY 10282

TQ11211 D2

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (ppm)	FLOW AFTER (ppm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
1	Piez # 25 North Exit of Stuyvesant H.S.	0800	1600	3	3	1440	0	0	218.52	218.52
2	North west site	0801	1601	3	3	1440	0	0	218.52	218.52

TECHNICIAN: DIMITRIOS M. SALIC

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX RESULTS TO	RECEIVED AT LAB BY:
	N.Y.C. D.D.C.	SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME:

ANALYST:

DATE RECEIVED: 12/11/01

DATE OF ANALYSIS 12/12

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356

CITY_21MC100_002988248

NYC-WTC_000205391

12/12/2001 13:01 7187293774

KAM CONSULTANTS

PAGE 01/03