NYC 9/11 Public Portal Document

KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTOL FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12/13/01
ADDRESS: 345 Chambers St., NY,NY 10282

TO1214 B

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED 0.5-5.0 (μ)	STRUCTURES DETECTED >5.0 (μ)	Structure Density (struc/mm²)	Structure Concentration (struc/cc)
1	Piez #25 NOTH EXIT OF Stuyvesant H.S.	8011	1600	3	3	1428	0	0	<16.67	<0.0041
2	North west site	8:05	1601	3	3	1428	0	0	<16.67	<0.0041

RECEIVED
KAM CONSULTANTS
2001 DEC 13 PM 5:26

TECHNICIAN: D. SALIS

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX Results TO N.Y.C. D.D.C	RECEIVED AT LAB BY: SAMPLE CONDITION UPON RECEIPT: DATE/TIME:

ANALYST:

DATE RECEVED: 12/18

DATE OF ANALYSIS 12/19

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RSULTS TO (212) 941-5356

12/14/2001 13:02 7187293774 KAM CONSULTANTS PAGE 01/02
CITY_21MC100_002988254
NYC-WTC_000205392