



KAM CONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12-17-01
ADDRESS: 345 Chambers St., NY, NY 10282

To 11217C

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (fibers/mm ³)	Structure Concentration (fibers/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
	PIER 25									
1	North Entrance of school - East	00.02	8.01	3	3	1437	0	0	4/6 67	10,004
2	11 ——— " ——— West	00.03	8.02	3	3	1437	↓	↓	↓	↓

RECEIVED
KAM CONSULTANTS
2001 DEC 17 AM 9:37

TECHNICIAN: Renata Dymkowska

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX results to DDC.	RECEIVED AT LAB BY: MLC
		SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME: 2/17

ANALYST: ALEXS BARENGOVS DATE RECEIVED: 12-17 DATE OF ANALYSIS 12-17

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)
Sample Volume may be below recommended limit of the method.
FAX RESULTS TO (212) 941-5356

CITY_21MC100_002988265