

PAGE 01/03

KAM CONSULTANTS

7187293774

12/23/2001 12:28

CITY_21MC100_002988281



35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT: Stuyvesant H.S.

SAMPLING DATE: 12/22/01
ADDRESS: 345 Chambers St., NY, NY 10282

T011223 B

FIELD DATA							LAB ANALYSIS			
SAMPLE #	LOCATION	TIME IN	TIME OUT	FLOW BEF (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	STRUCTURES DETECTED		Structure Density (struc/mm ²)	Structure Concentration (struc/cc)
							0.5-5.0 (μ)	>5.0 (μ)		
1	Pier # 25 North Exit of Stuyvesant H.S.	0801	1600	3	3	1437	0	0	4667	200040
2	North West Site	0802	1601	3	3	1437	1	1	↓	↓

RECEIVED
KAM CONSULTANTS
20 DEC 23 AM 10:30

TECHNICIAN:

D. SALIS

ROTAMETER: KAM101

CHAIN OF CUSTODY	FAX results TO	RECEIVED AT LAB BY: JLL
	N.Y.C. D.D.C.	SAMPLE CONDITION UPON RECEIPT:
		DATE/TIME: 12/23

ANALYST:

ALEX B. KATZ

DATE RECEIVED:

12-23

DATE OF ANALYSIS

12-23

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) EPA 40 CFR Part 763 (AHERA)

Sample Volume may be below recommended limit of the method.

FAX RESULTS TO (212) 941-5356