

KAMCONSULTANTS
35-40 36th Street
Long Island City
New York, 11106
Tel: (718) 729-1997
Fax: (718) 729-1876

CHAIN OF CUSTODY FOR ASBESTOS AIR MONITORING

CLIENT: NYC-DDC
PROJECT:
STUYVESANT H.S.

SAMPLING DATE: 11-04-01 sun
ADDRESS: 345 CHAMBERS STR
N.Y. N.Y. 10282

N.Y. N.Y. 10282 TOLLIOSA

FIELD DATA									LAB ANALYSIS				
SAMPLE ID#	TYPE	LOCATION	R E S P	W O R K	TIME IN PM	TIME OUT	FLOW BEF. (lpm)	FLOW AFTER (lpm)	VOLUME (liters)	FIBERS PER FIELD VIEW	FIBERS PER CC	LAB ID #	CASSETTE 25MM 37MM
1		PIER # 25			4:05	23.58	3	3	1419	4667	40.0	045	TEST METHOD: PCM ☒ TEM
2		PUMP # 2 - OUTSIDE NORTH ENTRANCE OF SCHOOL - E -			4:07	23.59	3	3	1416	1	↓		TURN-AROUND TIME: ☒ IMMEDIATE 24-HOUR 24-HOUR OTHER: 2001 NOV - 5 AM
													ANALYST: W. Mark
													DATE OF ANALYSIS: 11/5/01
													TIME OF ANALYSIS: 1045

SAMPLE TYPE:

A=BACKGROUND, B=PREABATEMENT, C=DURING ABATEMENT, D=POST-ABATEMENT
E=OUTSIDE WORK AREA, F=INSIDE WORK AREA, G=MICROTRAP EXHAUST DISCHARGE
H=DECONTAMINATION FACILITY, I=CRITICAL BARRIER, J=OUTSIDE BLDG, K=FIELD BLANK
L= AIR QUALITY, M=COMPLIANCE MONITORING

TYPE OF RESPIRATORS:

1 = HALF FACE, 2 = PAPR, 3 = TYPE C, 4 = OTHER (SPECIFY):

TYPE OF WORK:

1= BLDG DECON, 2 = PLASTICIZING, 3 = GROSS REMOVAL, 4 = GLOVEBAG, 5 = CLEANING, 6 = ENCAPSULATION, 7 = BAGOUT, 8 = OTHER (SPECIFY):

TECHNICIAN: ZB. NOWALK / A. MARTIROSSIAN

ROTAMETER: *LOW 60*

PAGE 1 OF 1

CHAIN OF CUSTODY	RELINGUISHED BY:	COMMENTS:	RECEIVED AT LAB BY:
	METHOD OF SHIPMENT:		SAMPLE CONDITION UPON RECEIPT:
	DATE/TIME:		DATE/TIME: